Form 3160-5 (June 1990)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

R	ECE	IVE	D

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AN	ID REPORTS ON WELLS	IVED NM-03188	
Do not use this form for proposals to drill	or to deepen or reentry to a different reserve	6. If Indian, Allottee or Tribe Name	
	PERMIT - " for such proposals 98 DEC	PH 12: DC	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation	
1. Type of Well	070 FARMIN	GTON, Non Juan 29-5 Unit	
Other	and the same in the little	8. Well Name and No.	
2. Name of Operator	<u> </u>	S 1 20 5 Unit #00	
Phillips Petroleum Company	ner a anno	SJ 29-5 Unit #28  9. API Well No.	
3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farming	TOP NM 97401 FOE FOO 24F4	30-039- 07563	
4. Location of Well (Footage, Sec., T., R., M., or Survey De		10. Field and Pool, or exploratory Area	
Unit M, 990' FSL & 990' FWL	Vo Blanco Mesaverde		
Section 20, T29N, R5W	DIST. 3	11. County or Parish, State	
	1	Rio Arriba, NM	
12. CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE, RE	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION		
X Notice of Intent	Abandonment	Change of Plans	
	Recompletion	New Construction	
Subsequent Report	Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair	Water Shut-Off	
Final Adandonment Potice	Altering Casing	Conversion to Injection	
	X Other Add pay & stim	Dispose Water (Note: Report results of multiple completion on Well	
3. Describe Proposed or Completed Operations (Clearly state all	nertinent details, and give pertinent dates, including estimated d	Completion or Recompletion Report and Log form.)	
give subsurface locations and measured and true verti	cal depths for all markers and zones pertinent to this work.)*	are of starting any proposed work. If well is directionally diffie	
MIRU. ND WH & NU BOPs. POOH w/prod	duction tubing. Isolate existing Mesa	averde perfs with bridge plug.	
PI casing. If casing fails test -	isolate failure. Remediate with cemer	nt.	
If well records indicate no cement a	across the Lewis Shale interval, it ma	av he necessary to run a casing	
bond long (CBL). Shoot squeeze ho	les in casing and pump sufficient volu	The of cement to cover and	
isolate the Lewis Shale.			
Ponfonato and stimulate the Louis Ch	solo (soufe to be determined often le		
plug and run production tubing. Flo	nale (perfs to be determined after log ow test the lewis Shale	gs are run). Retreive bridge	
Fire and van production out ing.	w desc the Lewis Share.		
A workover pit may be required.			
14. I hereby certify that the foregoing is true and correct	4.7		
Signed Fatsy (Mg)	Title Regulatory Assistant	Date12/11/98	
(This space for Federal or State office use)		DEC   6 1998	
Approved by ST Duane W Spencer	m'u	DEO 1 0 1998	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. \* See Instruction on Reverse Side



Conditions of approval, if any: