



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT  
Farmington Resource Area  
1235 Laplata Highway  
Farmington, New Mexico 87401



IN REPLY REFER TO:

NM-05220 et al. (WC)  
3162.3-1 (019)

Phillips Petroleum Company  
5525 Hwy 64 NBU 3004  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 248 SJ 29-6 Unit, sec. 15, T. 29 N., R. 6 W., Rio Arriba Co., NM,  
lease NM-05220.
2. 253 SJ 29-6 Unit, sec. 29, T. 29 N., R. 6 W., Rio Arriba Co., NM,  
lease NM-03040-A.
3. 251 SJ 29-6 Unit, sec. 23, T. 29 N., R. 6 W., Rio Arriba Co., NM,  
lease SF-078284.
4. 250 SJ 29-6 Unit, sec. 23, T. 29 N., R. 6 W., Rio Arriba Co., NM,  
lease SF-078284.
5. 214 SJ 30-5 Unit, sec. 5, T. 30 N., R. 5 W., Rio Arriba Co., NM,  
lease SF-080066.
6. 212 SJ 32-7 Unit, sec. 23, T. 32 N., R. 7 W., San Juan Co., NM,  
lease SF-078472.

As discussed with Gail Bearden of your company on, September 25, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

## ABANDONED LOCATION

OCT. 03 1991

**RECEIVED**  
OCT 4 1991  
OIL CON. DIV.  
DIST. 3

office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller  
Chief, Branch of Mineral Resources

Enclosures

cc:

~~New Mexico Oil Conservation Division~~, 1000 Rio Brazos Rd., Aztec, NM 87410