

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-1043

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Navajo Table Mesa

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Undesignated Paradox

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 27, T-28-N, R-17-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1. OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR  
SUN OIL COMPANY - DX Division

3. ADDRESS OF OPERATOR  
P. O. Box 1416, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

790' FSL, 1980' FEL, Sec. 27, T-28-N, R-17-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5363 KB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Estimated starting time: 6/30/69.

Well has reached its economic limit (11 BOPD, 1340 BWPD).

1. Pull tubing and pump.

2. Load hole w/mud.

3. Squeeze perfs @ 7295-7300' w/50 sx. through 2 3/8" tubing.


4. Cut 5 1/2" csg w/jet cutter @ approx. 5975' and POOH.

5. Set 25 sx plug over SWD perfs (5505-25') w/tubing from 5450 to 5550.

6. Set 15 sx plug in 9 5/8" csg from 70' to surface.

7. Install dry hole marker.

8. Clear location and make ready for inspection by 7/15/69 est.



U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED J.B. Hille J.B. Hille

TITLE Acting District Engineer

DATE 6/16/69

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

**General:** This form is designed for submitting proposals for abandonment of wells, operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, location, and should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.