

F 30-039-24799 6-18-90

F. Loc. 2205/S; 915/W Elev. 6270 GL Spd. Cu. ft. ID Cu. ft. PB
Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T
Csg. Perf. Prod. Stim. Grav. 1st Del. Gas 1st Del. Oil

BO/D		MCF/D After		Hrs.	SICP	PSI After	Days GOR		TEST DATA					Ref. No.	
TOPS		NID X		Well Log		Schd.		PC	Q	PW	PD	D			
Ojo Alamo		C-103		Plot X											
Kirtland		C-104		Electric Log											
Fruitland				C-122											
Pictured Cliffs		Ditr		Dfa											
Chacra		Datr		Doc											
Cliff House															
Menefee															
Point Lookout															
Mancos															
Gallup															
Greenhorn															
Dakota															
Entrada															
														Acres W/320	

P Basin Fr. Coal Co. RA S 08 T 29N R 07W U L Oper. Meridian Oil Inc. Loe. San Juan 29-7 Unit No. 520



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

TAKE
PRIDE IN
AMERICA

IN REPLY REFER TO:

SF-077842 et al. (WC)
3162.3-1.0 (019)

SEP. 24 1991

RECEIVED

SEP 25 1991

OIL CON. DIV.
(DIST. 3)

Meridian Oil Inc.
P.O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 724 Trigg, sec. 25, T. 31 N., R. 9 W., San Juan Co., N.M., lease SF-080876.
2. 200 SJ 28-5 Unit, sec. 14, T. 28 N., R. 5 W., Rio Arriba Co., N.M., lease SF-079250.
3. 100 Thompson, sec. 27, T. 31 N., R. 12 W., San Juan Co., N.M., lease NM-01614.
4. 520 SJ 29-7 Unit, sec. 8, T. 29 N., R. 7 W., Rio Arriba Co., N.M., lease SF-078423.
5. 204 SJ 28-4 Unit, sec. 19, T. 28 N., R. 4 W., Rio Arriba Co., N.M., lease NM-03862.
6. 508 SJ 29-7 Unit, sec. 15, T. 29 N., R. 7 W., Rio Arriba Co., N.M., lease SF-077842.
7. 710 Lackey B, sec. 27, T. 28 N., R. 9 W., San Juan Co., N.M., lease SF-077107A.

As discussed with John Caldwell of your company on, September 20, 1991, the subject APDs are rescinded and returned due to drilling not being commenced within the approved period of time.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

~~1000 Rio Brazos Rd. Aztec, NM 87410~~
~~US Fish and Wildlife Service~~
~~Wildlife Conservation Division~~