

BURLINGTON RESOURCES

SAN JUAN DIVISION

November 11, 2002

Mr. Charlie Perrin
New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, New Mexico 87410

Re: San Juan 29-7 Unit #56
CTP0219720112 ~~022006 0202607633~~
30-039-60102 021978812
SF-077842
990'FNL, 990'FEL, Section 15-29-7

Dear Mr. Perrin:

Thank you for the opportunity to meet with you concerning bradenhead issues, including the above referenced well.

The San Juan 29-7 Unit #56 well has pressure on the intermediate but not on the bradenhead. The intermediate casing string is landed into the Lewis and the top of cement on the production string covers the Cliff House. See the attached wellbore schematic for more detail.

There is no contamination of fresh waters as evidenced by the lack of bradenhead pressure.

Since the well is located north of the Chacra line, there is only one zone exposed. Therefore correlative rights are protected and we believe no remedial action is necessary.

We would appreciate your looking at the information we have provided and letting us know that you agree.

Again, we appreciate your time and efforts in working with us on these issues.

Sincerely,


Peggy Cole
Regulatory Supervisor

Xc: Bureau of Land Management -- Farmington
Matt Roberts -- Burlington
Wayne Fletcher -- Burlington
Wellfile

OIL CONSERVATION DIVISION

API # 30-039-60102

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5/28/2002 Operator Burlington Resources Oil & Gas
Lease Name SAN JUAN 29-7 UNIT Well No 56 Location: U A Sec. 15 Twp. 029N Rge. 007W
Pressure (Flowing) Dwt Tubing 132 Intermediate 142 Casing 142 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING	FLOWED:	FLOWED:
5 Min.	142	142	Steady Flow	X
10 Min.	0	0	Surges	
15 Min.	0	0	Down to Nothing	
20 Min.	0	0	Nothing X	
25 Min.	0	0	Gas	X
30 Min.	0	0	Gas & Water X	
			Water	

If Bradenhead flowed water, check description below:

Clear
Fresh
Salty
Sulfur
Black

Remarks:

BH- 0#psi. INT- 142# at start of test. Blew
INT30mins psi came down to 96#psi. SI for
5mins INT psi came back up to
128#psi.

By MATT CRANE 358

Lease Operator

Position

Witness

SAN JUAN 29-7 UNIT 56

WellView - Schematic

Asset ID Number 6935000	Property Number 002342100	Operator BURLINGTON RESOURCES O&G CO LP	County RIO ARRIBA	State NM
KB Elev (ft) 6228.00	Ground Elev (ft) 6218.00	KB-Ground Distance (ft) 10.00	Plug Back 5,410.0	Total Depth (ftKB)
Spud Date 1/7/57	Surface Legal Location Sect: 015, Twp: 029N, Rg: 007W, Poly: A, NMPM	NS Dist. (ft) 990.0	NS Flag FEL	EW Dist. (ft) 990.0
		EW Flag FNL	Latitude (DMS) 36° 43'	Longitude (DMS) 107° 33'
			49.404" N	9.216" W

Schematic

