DISTRIBUTION SANTA FE  U.S.G.S.  LAND OFFICE OPERATOR  NEW MEXICO OIL CONSERVATION COMMISSION	Form C-1/03 Supersedes Old C-102 and C-103 Effective 1-1-65  5a. Indicate Type of Lease State Federal Fee.  5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1.  OIL GAS WELL OTHER.	7. Unit Agreement Name
2. Name of Operator	San Juan 29-7 Unit
El Paso Natural Gas Company  3. Address of Operator	San Juan 29-7 Unit
Box 990, Farmington, New Mexico 87401	87
UNIT LETTER G 1450 FEET FROM THE NORTH LINE AND 1750 FEET FROM	Rianco Mesa Vende
THE East LINE, SECTION 19 TOWNSHIP 29N RANGE 7W NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 6665' GL	12. County Rio Arriba
Check Appropriate Box To Indicate Nature of Notice, Report or Otl NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.  PULL OR ALTER CASING CHANGE PLANS CASING TEST AND EMEN OF THE PUBLIC PROPERTY OF THE PUBLIC	970 PLUG AND ABANDONMENT
OIL CON C	
	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent aries, including	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, an	est hated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, work) SEE RULE 1703.  In order to increase production it is planned to workover and restimute following manner:	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, an	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, and give pertinent details, work) SEE RULE 1703.  In order to increase production it is planned to workover and restimate following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casi 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casi cement retailer near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the leaks.	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details, an	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent ares, including work) SEE RULE 103.  In order to increase production it is planned to workover and restimate following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casi 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casi cement retainer near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the bottom, no additional block squeeze of the 7" annulus is planned. If there are noleaks near the base of the Ojo Alamo formation, performed the base of the Ojo Alamo formation & block squeeze the 7" annulus sacks of cement.	ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at w/approximately 125
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent ares, including work) SEE RULE 1703.  In order to increase production it is planned to workover and restimate following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casis 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casis cement retainer near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the beformation, no additional block squeeze of the 7" annulus is planned. If there are noleaks near the base of the Ojo Alamo formation, perfor the base of the Ojo Alamo formation & block squeeze the 7" annulus sacks of cement.  Clean out if hole conditions permit, otherwise sidetrack & redrill to Run a full string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the sufficient amount of cereating an	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at w/approximately 125 approximately 5800'.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details.  In order to increase production it is planned to workover and restiming following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casis 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casis cement retails near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the besondation, no additional block squeeze of the 7" annulus is planned. If there are noleaks near the base of the Ojo Alamo formation, performed the base of the Ojo Alamo formation & block squeeze the 7" annulus sacks of cement.  Clean out if hole conditions permit, otherwise sidetrack & redrill to Run a full string of 4 1/2" production casing & sufficient amount of casing shoe. Selectively perf. & sand—water fracture the Meea Verger 18, I hereby certify that the information above is true and complete to the best of my knowledge and belief.	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at w/approximately 125 approximately 5800'.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent ares, including work) SEE RULE 1703.  In order to increase production it is planned to workover and restimate following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casis 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casis cement retainer near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the beformation, no additional block squeeze of the 7" annulus is planned. If there are noleaks near the base of the Ojo Alamo formation, perfor the base of the Ojo Alamo formation & block squeeze the 7" annulus sacks of cement.  Clean out if hole conditions permit, otherwise sidetrack & redrill to Run a full string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the string of 4 1/2" production casing & sufficient amount of cereating and the sufficient amount of cereating an	estimated date of starting any proposed ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at w/approximately 125 approximately 5800'.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent details.  In order to increase production it is planned to workover and restimate following manner:  Pull tubing, set a drillable bridge plug near the bottom of the 7" casing to 1000 psi.  If tubing is stuck, cut off tubing approximately 100' below the 7" casing cement retailer near the bottom of the 7" casing, squeeze the open 200 sacks of cement.  Pressure test the 7" casing to 1000 psi.  Isolate & squeeze cement any leaks. If leaks are squeezed near the beson formation, no additional block squeeze of the 7" annulus is planned. If there are noleaks near the base of the Ojo Alamo formation, performed the base of the Ojo Alamo formation & block squeeze the 7" annulus sacks of cement.  Clean out if hole conditions permit, otherwise sidetrack & redrill to a Run a full string of 4 1/2" production casing & sufficient amount of casing shoe. Selectively perf. & sand—water fracture the Mesa Verger 18, I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Crignal Signal F. H. WOOD	ulatethis well in the ing & pressure test to ing shoe, set a drillable hole w/approximately pase of the Ojo Alamo rate 2 squeeze holes at w/approximately 125 approximately 5800'.