NO. OF COPIES RECEIVED 3	
DISTRIBUTION	Form C-103 Supersedes Old
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE / / WEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	Eq. Indiante Time of L
LAND OFFICE	State Redered Fee
OPERATOR /	State Federal Fee 5. State Oil & Gas Lease No.
	s. State on & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL GAS WELL WELL WELL OTHER.	7. Unit Agreement Name
Name of Operator	8. Farm or Lease Name
El Paso Natural Gas Company	Roelofs
Address of Operator	9. Well No.
Box 990, Farmington, New Mexico	2
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER A . 990 FEET FROM THE NORTH LINE AND 1650 FEET	Blanco Mesa Verde
FIRE OND	
THE East LINE, SECTION 15 TOWNSHIP 29N RANGE 8W	NMPM.
15. Elevation (Show whether DF, RT, CR, etc.)	12. County
6341 ' DF	San Juan
ERFORM REMEDIAL WORK  EMPORARILY ABANDON  ULL OR ALTER CASING  CHANGE PLANS  CASING TEST AND CEMENT JOB  OTHER	OIL CON. COM.
OTHER Case, Cement & Fracture treat	DIST. 3
Describe Proposed or Completed Operations (Clearly state all partir and descite and descit	
7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incl work) SEE RULE 1703.	luding estimated date of starting any propo
In order to increase deliverability it is indended to workov wellin the following manner:	
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of	er and restimulate this
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkxxxx at approximat
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stri	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkmims at approximat
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stricasing and sufficient cement to cover the 7" casing shoe. Selectively perforate and frac the Mesa Verde formation. In the event the tubing is stuck and has to be cut off or if	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xxxxxx at approximat sacks of cement. ng of 41," production
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stricasing and sufficient cement to cover the 7" casing shoe. Selectively perforate and frac the Mesa Verde formation. In the event the tubing is stuck and has to be cut off or of hole makes a clean out uneconomical a drillable cement retain the bottom of the 7" casing and the open hole squeezed with:	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkmims at approximat sacks of cement. ng of 4 1/" production other lunk in the open ner will be set near approximately 250
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stricasing and sufficient cement to cover the 7" casing shoe. Selectively perforate and frac the Mesa Verde formation. In the event the tubing is stuck and has to be cut off or of hole makes a clean out uneconomical a drillable cement retain the bottom of the 7" casing and the open hole squeezed with sacks of cement. A new sidetracked hole will be drilled to	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkmims at approximat sacks of cement. ng of 4 1." production other lunk in the open ner will be set near approximately 250
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stricasing and sufficient cement to cover the 7" casing shoe. Selectively perforate and frac the Mesa Verde formation. In the event the tubing is stuck and has to be cut off or of hole makes a clean out uneconomical a drillable cement retain	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkmims at approximat sacks of cement. ng of 4 1/" production other unk in the open ner will be set near approximately 250
In order to increase deliverability it is indended to workov wellin the following manner:  Pull tubing, set a drillable bridge plug near the bottom of test to 1000 psi.  Isolate and squeeze any leaks. If leaks occur between 2000' of the 7" annulus is planned. If there are no leaks, perfor 2150' and block squeeze the 7" annulus with a minimum of 100 Clean out and drill to approximately 5450'. Run a full stricasing and sufficient cement to cover the 7" casing shoe. Selectively perforate and frac the Mesa Verde formation. In the event the tubing is stuck and has to be cut off or of hole makes a clean out uneconomical a drillable cement retain the bottom of the 7" casing and the open hole squeezed with sacks of cement. A new sidetracked hole will be drilled to	er and restimulate this the 7" casing and pressur and 2900' no block squee ate 2xkmims at approximat sacks of cement. ng of 4 1/" production other lunk in the open ner will be set near approximately 250

Petroleum Engineer

SUPERVISOR DIST. #3

10-5-66

OCT 11 1966