UNITED STATES DEPARTMENT OF THE INTERIOR

Dec. 1973	E LEASE SE SE SE SE SE
UNITED STATES	5. LEASE # 2 6 8 8
DEPARTMENT OF THE INTERIOR	5. LEASE
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	Bago o _k a
	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	He had be seen a
to a present to drill or to deepen or plug back to a unificent p	8. FARM OR LEASE NAME
Do not use this form for proposals to drill see the see that s	A. L. Elliott "Ches
1. oil gas x other	9. WELL NO. 25 25 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Mell — Mell	1
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
AMOCO PRODUCTION COMPANY	Blanco Mesaverde
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
501 Airport Drive Farmington, NM 87401	AREA NW/4 NE/4 Section 15,
4 LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	T-29-N, R-9-W
below.) 990' FNL x 1650' FEL, Section 13,	12. COUNTY OR PARISH 13. STATE
AT SURFACE: T_29_N R-9-W AT TOP PROD. INTERVAL: Same	- 3 5 3
AT TOP PROD. INTERVAL: Same	San Juan No.
AT TOTAL DEPTH:	1 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-045-08377
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	59 37 GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone
REPAIR WELL	change on Form 9-330.)
PULL OR ALTER CASING UMLTIPLE COMPLETE	그
CHANGE ZONES	
ABANDON*	
(other)	아마 아무리를 다리 학생들은 다.
	te all pertinent details, and give pertinent dates,
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly starincluding estimated date of starting any proposed work. If well is a including estimated date for all markers and zones pertine	directionally drilled, give subsurface locations and
including estimated date of starting any proposed work. If well is to measured and true vertical depths for all markers and zones pertine	ent to this work.)*
Measured and Market	+ voll as follows:
Amoco Production Company repaired the subjec	Well as 1011000
	well tubing stuck; cut 2-3/8"
1) Moved in service unit on 4/7/79. Found	Well tubing stuck, cut is
tubing at 4689', 4504' and 4508 ·	이 얼마를 하고 있는 얼마를 즐겁는데
2) Fished 2-3/8" tubing out of hole.	S Table OK
of Car bailed plug at 4190' and pressure te	ested tubing and casing, neid on.
4) Drill out bridge plug and cleaned up wel	1 1.
1 - 1 1/18//4	
6) Well back on sales line 4/10/77.	
	The state of the s
	OR Sept on Ft
Subsurface Safety Valve: Manu. and Type	AX COLLEGE BY
18. I hereby certify that the foregoing is true and correct	015 F V 10 170 F 10 10 10 10 10 10 10 10 10 10 10 10 10
SIGNED TITLE Dist. Adm.	Supvr. DATE
SIGNED	
(This space for Federal or State office use)	
	DATE