Form 3160-5 (June 1990)

Approved by

Conditions of approval, if any:

## **UNITED STATES**

FORM APPROVED

	RTMENT OF THE INTERIOR U OF LAND MANAGEMENT	Budget Bureau No. 1004-0135 Expires: March 31, 1993
Do not use this form for prope	TICES AND REPORTS ON WELLS  osals to drill or to deepen or reentry to a different reservation FOR PERMIT - " for such proposals	5. Lease Designation and Serial No.  SF-076337  6. If Indian, Allottee or Tribe Name
		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gee Well Well Other		8. Well Name and No.
2. Name of Operator	Attention:	W.D. Heath /A/ 14
Amoco Production Company	Patty Haefele	9. API Well No.
3, Address and Telephone No.	- Totty House	2004522002
P.O. Box 800, Denver, Colorado	80201 (303) 830-4988	3004523902 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or	Survey Description)	Manzanares-Farmington
45001501 0001514	0 - 0 T 20N D 0W	11. County or Parish, State
1530' FSL 980' FWL	Sec. 9 T 29N R 9W Unit	San Juan New Mexico
12. CHECK APPROPRIA	ATE BOX(s) TO INDICATE NATURE OF N	
TYPE OF SUBMISSION	<del></del>	OF ACTION
	Abandonment	Change of Plans
Notice of Intent	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Subsequent Report	☐ Casing Repair ☐ Altering Casing	Water Shut-Off
Final Abandonment Notice	Other	Conversion to Injection Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (C	Clearly state all pertinent details, and give pertinent dates, including estimat	ed date of starting any proposed work . If well is directionally drilled, give
subsurface locations and measured and true	vertical depths for all markers and zones pertinent to this work,)*	
Amoco Production Company	has plugged and abandoned the subject well us	ing the following procedures:
	OH. Lay down 1.25" tubing. TIH with 2.375" rom 2060' to 771 ft. WOC for 48 hrs. TIH. T	tubing. Tag 2060' cement with 375 sx 65/35 poz
110 sx Class B neat. C	Circulate 3 bbls cement to surface. Nipple down all P&A marker. RDMOSU - 5/15/95.	•
110 sx Class B neat. Cut off wellhead. Insta	Circulate 3 bbls cement to surface. Nipple down	1 BOP.
110 sx Class B neat. C Cut off wellhead. Insta	Circulate 3 bbls cement to surface. Nipple down all P&A marker. RDMOSU - 5/15/95.	RECEIVE SS JUN 15 1
110 sx Class B neat. C Cut off wellhead. Insta	Approved as to plugging of the well to be be believed as to plugging of the well to be believed as to plugging of the well to be believed as to plugging of the well to be believed as to plugging of the well to be believed as to plugging of the well to be believed.	RECEIVED RECEIVED OF FARMUNCION

APPROVED