

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.

SF-080246

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Florance 119

9. API Well No.

30-045-23976

10. Field and Pool, or Exploratory Area

Basin Dakota

11. County or Parish, State

San Juan, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Amoco Production Company ATTN: J.L. HAMPTON

3. Address and Telephone No.

P. O. Box 800 Denver, Colorado 80201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1085' FNL, 800' FEL NW/NE Sec. 22, T29N, R9W

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Amoco Production Company intends to abandon the Dakota formation in the subject well and Recomplete (plug back) to the Fruitland Coal formation per the attached procedure.

Please contact Cindy Burton (303)830-5119 if you have any questions.

RECEIVED  
SEP 25 1991  
OIL CON. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed J.L. Hampton/ab

Title Sr. Staff Admin. Supervisor

Date 9/13/91

(This space for Federal or State office use)

Approved by \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

Conditions of approval, if any: \_\_\_\_\_

Florance 119  
22A-29N-09W  
Basin Dakota PxA  
&  
Basin Fruitland Recompletion

1. Check location for anchors. Install if necessary. Test anchors.
2. MIRUSU. Blow well down. Kill if necessary w/ 2% KCl. NDWH. NUBOP.
3. POOH w/ 2-3/8" tbg. TIH w/ tbg and cmt retainer. Set retainer @ 6350'. Squeeze perforations w/ 120 cu.ft. Class B cement. Sting out of retainer and leave cmt to 6300'. (20 cu.ft.)
4. Load hole w/ 9 ppg mud. POOH.
5. RIH w/ wireline and perforate four squeeze holes @ 4500' and 3900'. TIH w/ tbg and cmt retainer and set @ 3800'. Squeeze perforations w/ 102 cu.ft. Class B cmt. Sting out of retainer and spot cmt to 2500'. (115 cu.ft.) WOC.
6. TIH and tag TOC. Circulate hole clean. POOH.
7. Fill csg w/ 2% KCl water. Run cased hole CNL/GR/CCL log from 2400' to 1500'. Fax copy to Denver immediately for review. Contact Denver for perforation intervals.
8. Pressure test csg to 3000 psi. Report any problems to Denver.
9. Once perforation intervals are selected, TIH w/ 4" perforating gun, 90° phasing, minimum 22 gram charge. Perforate intervals w/ 8 JSPF. POOH.
10. Fracture stimulate down casing w/ slick water and 20/40 frac sand. (Procedure to follow) Shut well in for a minimum of 4 hours.
11. Flow well back slowly, attempting to avoid sand production.
12. TIH w/ 1-1/4" tbg. Circulate out fill to PBTD. Land tbg. (dependent upon perforation intervals) Swab well if necessary.
13. RDMOSU. Return well to production.
14. Report gas and water rates on morning wire for 2 weeks. Take wellhead gas and water samples. Submit for analysis.

Report any major problems to Ty Smith @ (303) 830-5164