State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and Re	ports on Wells		
		API	# (assigned by OCD) 30-039-07737	
1. Type of Well GAS		5.	Lease Number	
		6.	State Oil&Gas Lease	
2. Name of Operator		7.	E-347 Lease Name/Unit Name	
BURLINGTON				
RESOURCES OIL &	GAS COMPANY	_	San Juan 30-6 Unit	
3. Address & Phone No. of Operat	or	8.	Well No. #13	
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.		
4. Location of Well, Footage, Se			Elevation:	
1500'FNL 1600'FEL, Sec.32, T-	30-N, R-6-W, NMPM, Rio	Arriba County		
Type of Submission	Type of Act			
X Notice of Intent		Change of Pla New Construct		
Subsequent Report	Plugging Back	Non-Routine		
Dinal Abandan	Casing Repair	Water Shut o		
Final Abandonment	Altering Casing X Other -	Conversion to	o injection	
It is intended to repair t attached procedure	and wellbore diagram.	MAR - 4 1888		
SIGNATURE Students	(LTL7) Regulatory	Administrator_		
(This space for State Use)				
ORIGINAL SIGNED BY CHARLIE	T. PERRIN SEPUTY OIL & GA	s inspector, dist. 4	MAR -4 1999	

San Juan 30-6 Unit #13 Blanco Mesaverde

Unit G. Sec. 32, T-30-N, R-6-W

Latitude / Longitude: 36° 46.32936' / 107° 28.94076' Recommended Tubing Repair Procedure 2/16/99

Project Justification: During a workover in March 1994, the Cliff House, Menefee, and Lewis shale were added as producing intervals. In order to isolate the Lewis and conduct a production test, a packer was set in between the Cliff House and Lewis perforations; the main body of the Mesaverde was produced through the tubing, while the Lewis was produced through the tubing/casing annulus. The lease operator reports that the Mesaverde has recently begun having a problem with liquid loading. By removing the packer and flowing all gas production through the tubing, we will make it easier for the well to unload its own liquids.

NOTE: ALL DEPTHS ARE MEASURED FROM KB. KB to GL was 10'.

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Prior to moving in rig, 1. make one-call and then verify rig anchors and dig pit.
- 2. MIRU workover rig. NU relief line and blow well down (kill with 2% KCL water only if necessary). ND WH and NU BOP. Test and record operation of BOP rams. Replace any WH valves that do not operate properly. Test secondary seal and install or replace if necessary.
- 3. Mesaverde, 2-3/8", 4.7#, J-55 tubing set at 6108' (197 jts). Broach tubing and set tubing plug in F-nipple (1.81" ID) at 6077'. Release donut and pick straight up on 2-3/8" tubing to release 5-1/2" Baker Model R-3 packer (set with 13,000# compression). Lower tubing slightly to engage J-pin and the J-slot (this proceess prevents packer resetting during trip). TOOH and stand back 2-3/8" tubing. LD packer and sliding sleeve. Visually inspect tubing for corrosion, and replace any bad joints. Check tubing for scale and notify Operations Engineer and Drilling Superintendent if it is present.
- TIH with 4-3/4" bit, bit sub, and watermelon mill on 2-3/8" tubing and round trip to PBTD at +/- 6144', cleaning 4. out with air/mist. NOTE: When using air/mist, mist rate must not be less than 12 bph. Speak with Operations Engineer and Drilling Superintendent, and if necessary, determine the best way to remove scale from the casing and perforations.
- 5. TIH with one joint of 2-3/8" tubing with expendable check, F-nipple (one joint off bottom), then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing. Replace any bad joints. CO to PBTD with air/mist.
- PU above the top Mesaverde perforation at 4688' and flow the well naturally, making short trips for clean-up 6. when necessary.
- 7. Land tubing at 6030'. Obtain pitot gauge from casing and report this gauge. Broach the upper ½ of the production tubing. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. If well will not flow on its own, make swab run to SN. RD and MOL. Return well to production.

Operations Engineer:

L. Tom Loveland

Office 326-9771 Pager

324-2568

Home 564-4418

San Juan 30-6 Unit #13

Current -- 2/17/99 AIN: 6973801 MV

Blanco Mesaverde

1500' FNL,1600' FEL Sec. 32, T30N, R6W, Rio Arriba County, NM Longitude / Latitude: 36-46.33' /107-28.94'

