UNITED STATES

O.				
DEPARTME	ENT	OF	THE	INTERIOR
BUREAU	OF	LAI	M ON	anagement

Sundry Notices and Reports on Wells		
	5.	Lease Number SF-080180A
1. Type of Well GAS	6.	If Indian, All. or Tribe Name
2. Name of Operator	7.	Unit Agreement Name
RESOURCES OIL & GAS COMPANY	8.	San Juan 30-6 Unit Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 30-6 U #44 API Well No. 30-039-24247
4. Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
945'FNL, 1130'FEL, Sec.31, T-30-N, R-6-W, NMPM	11.	Basin Fruitland Coa County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, O	THER	DATA
Type of Submission Type of Action		
Notice of Intent Abandonment Change of		
Recompletion New Cons		
		Fracturing
Casing Repair Water SI	nut o	C E
Final Abandonment Altering Casing Convers		
Final Abandonment Altering Casing Convers		
Final Abandonment Altering Casing Convers: _X_ Other - Tubing change	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts : jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI	y val 2112' 2 7/8	ve. Pump 35 bbl . SDON. " tbg. TIH w/117
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 26-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts: jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI released. 14. I hereby certify that the foregoing is true and correct. Signed All Title Regulatory Supervisor	g val 2112' 2 7/8 D BOP	ve. Pump 35 bbl. SDON. "tbg. TIH w/117. NU WH. RD. Rig
Title Regulatory Supervisor Altering Casing Convers: X_ Other - Tubing change Altering Casing Convers: Altering Casing Conversed Altering Conversed Altering Casing Conversed Altering Conversed Altering Conversed Altering Conversed Altering Co	g val 2112' 2 7/8 D BOP	ve. Pump 35 bbl. SDON. "tbg. TIH w/117. NU WH. RD. Rig
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 2 6-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts: jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI released. 14. I hereby certify that the foregoing is true and correct. Signed Title Regulatory Supervisor no (This space for Federal or State Office use)	g val 2112' 2 7/8 D BOP	te 8/7/00
Final Abandonment Altering Casing Convers: X_ Other - Tubing change 13. Describe Proposed or Completed Operations 6-28-00 MIRU. ND WH. NU BOP. Tag up @ 3717'. Drop standing wtr down tbg. TOOH w/2 7/8" tbg. Locate hole @ 26-29-00 TIH w/2 7/8" tbg. PT tbg, failed. TOOH w/120 jts: jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 3711'. NI released. 14. I hereby certify that the foregoing is true and correct. Signed	g val 2112' 2 7/8 D BOP	ve. Pump 35 bbl. SDON. "tbg. TIH w/117. NU WH. RD. Rig