Submit 3 Copies to Appropriate

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office OIL CONSERVATION DIVISION DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 WELL API NO. 2040 Pacheco St. 30-039-24893 Santa Fe, NM 87505 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease STATE X  $_{\text{FEE}} \square$ DISTRICT III Sate Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR POPULATION FOR POPULATIO 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: San Juan 30-5 Unit WELL WELL X OTHER 017654 2. Name of Operator 8. Well No. Phillips Petroleum Company SJ 30-5 Unit #231 3. Address of Operator 9. Pool name or Wildcat 5525 Highway 64, NBU 3004, Farmington NM 87401 Basin Fruitland Coal 4. Well Location 879 South 952 Unit Letter Feet From The Line and Feet From The Line 32 30N 5W Rio Arriba Township Range County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB X <u>Recavitate well</u> OTHER: -OTHER: -12.. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Plans are to pull the tubing and liner and cleanout to TD, then recavitate the coal interval. We will RIH with a new 5-1/2" liner and perforate, land tubing and return well to production. A brief description of the work planned is as follows: MIRU. Install BPV & ND WH. NU & test BOP. Retrieve BPV. POOH w/tubing. RIH w/bit on 2-7/8" DP & cleanout to TD. RU and recavitate coal interval. POOH. RIH with new 5-1/2" 15.5# J-55 liner with hanger. Set liner on bottom. Set hanger. RU wireline and perforate the liner. RIH with tubing and land. Set BPV. ND BOP & NU WH. Retrieve BPV & return well to production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Regulatory Assistant SIGNATURE TITLE \_ DATE Patsy Clugston TYPE OR PRINT NAME 505-599-3454 TELEPHONE NO. (This space for State Use) DEPUTY OIL & GAS INSPECTOR, DIST. #5 TRIGINAL STONES BY SE US JAN

TITLE

DATE