92 JUN 29 AM 11: 47 P.O. Box 2038
Farmir (505) & MA
019 FARMINGTON, N.M.

(505) E Make 174.99

RAIS BRANCH

HILF 1 for

Jule DIP 2

ALL SUPV.

June 26, 1992

U.S. DEPARTMENT OF INTERIOR Bureau of Land Management 1235 La Plata Highway Farmington, New Mexico

Attn: John L. Keller

OIL CON. DIV.
DIST. 3

RE: Snyder Oil Long Term Shut In Wells

Dear John,

The letter received on May 20th was lost during a change in management and was brought to my attention by a phone conversation with Wayne Townsend on June 25, 1992.

Following is a request for classification of long term shut in for the following wells:

- Located in NW 1/4 Sec. 19, T31N, R12W, San Juan Co., N.M. This well is unable to produce in paying quantities due to high volumes of produced water and the high cost of water disposal. The well is currently being evaluated for installation of pump, rods, pump jack and water disposal system. Time is required to evaluate when this well can be put back into production.
- CAIN 1 Lease No. SF078464.
 Located in NW 1/4, Sec. 25, T31N, R13W, San Juan Co., N.M. Existing market conditions do not provide economics for change out of tubing and surface equipment. Time is required to evaluate when this well can be put back into production.
- Located in SW 1/4, Sec. 31, T29N, R10W, San Juan Co., N.M. Existing market conditions and high sales line pressures do not provide economics for change out of tubing and surface equipment. Time is required to evaluate when this well can be put back into production. SEE ATTACHED FOR APPROVED

CONDITIONS OF APPROVALAS AMENDED
Located in NW 1/4, Sec 31, T29N, R10W, San Jaan 541,20.1092

THIS APPROVAL EXPIRES MUL 0 1 1993

NMOCD

1113 APP

Page 2 - RE: SOCO Long Term Shut In Wells

Existing market conditions and high sales line pressures do not provide economics for change out of tubing and surface equipment. Time is required to evaluate when this well can be put back into production.

LINDA 1 - Lease No. I-149-IND-8469.
Located in SW 1/4, Sec. 31, T27N, R8W, San Juan Co., N.M.
Existing market conditions do not currently provide economics for re-stimulation of producing zones and purchase of production equipment. Time is required to evaluate when this well can be put back into production.

If you have further concerns or questions on this matter please call me at 632-8056.

Sincerely,

Chester L. Deal Superintendent

Chester L. & Jeal