Form 3160-5 (August 1999)

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

BORLAG OF EARLY WARMONIEMENT	5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS	NMSF080224
Oo not use this form for proposals to drill or to re-enter an	6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NMNM73835			
 Type of Well ☐ Oil Well ☐ Oth 	er				8. Well Name and N GALLEGOS CA		
2. Name of Operator Contact: MARY CORLEY BP AMERICA PRODUCTION CO E-Mail: corleym@bp.com					9. API Well No. 30-045-07832-00-S1		
3a. Address			(include area code .4491 0700	e)	10. Field and Pool, or Exploratory UNNAMED Basin Dak		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 27 T29N R12W NESE 1850FSL 1190FEL 36.69521 N Lat, 108.08125 W Lon					SAN JUAN COUNTY, NM		
12. CHECK APPF	ROPRIATE BOX(ES) TO	O INDICATE 1	NATURE OF 1	NOTICE, REF	PORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
■ Notice of Intent	☐ Acidize	□ Deep	en	☐ Production (Start/Resume)		□ Water Shut-Off	
_	☐ Alter Casing	☐ Fract	ure Treat	☐ Reclamat	ion	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomplete		☐ Other	
☐ Final Abandonment Notice	Change Plans	☑ Plug	and Abandon	☐ Temporarily Abandon			
	☐ Convert to Injection	☐ Convert to Injection ☐ Plug Back ☐ Water Disposal		sposal			
following completion of the involved testing has been completed. Final A determined that the site is ready for the subject well was approved Please note the change in proprocedure.	bandonment Notices shall be f final inspection.) d on 10/15/2001 for reco	iled only after all	requirements, incl ne Otero Chac	uding reclamation	n, have been comple	n 3160-4 shall be filed once eted, and the operator has	
					C OF ST		
14. I hereby certify that the foregoing i	s true and correct. Electronic Submission For BP AMERIC Committed to AFMSS for	A PRODUCTION	N CO, sent to th	he Farmington		9,30	
Name (Printed/Typed) MARY CO	ORLEY		Title AUTHO	ORIZED REP	RESENTATIVE		
Signature (Electronic	Submission)	į	Date 05/23/2002				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By			Title		Dat	e6/19/02	
Conditions of approval, if any, are attach ertify that the applicant holds legal or eather would entitle the applicant to concept.	quitable title to those rights in t	es not warrant or the subject lease	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan Basin Well Work Procedure

Well Name: GCU Com D 160

Version: #

Date: 5/22/2002

Repair Type: Plug and abandonment

Objectives:

Plug and abandonment procedure

- 1. Contact Federal and State agencies prior to starting P&A work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM 505-599-8907).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-3/8" tbg, visually inspecting.
- 7. TIH with CIBP on tbg. Set CIBP at 5800' to abandon the DK perfs.
- 8. Spot 12 sack cmt plug 5650' 5800' to isolate the DK.
- 9. Spot 12 sack cmt plug 4900' 5050' to isolate the GP.
- 10. Spot 12 sack cmt plug 2750' 2900' to isolate the MV.
- 11. Spot 12 sack cmt plug 1200' 1350' to isolate the PC.
- 12. Spot 12 sack cmt plug 650' 800' to isolate the FT.
- 13. Perf 4-1/2" csg @ 375' w/ 4 SPF. Attempt to circulate to surface. Sqz with 100 sxs, leaving 28 sacks inside csg.
- 14. ND BOP. Cut off WH. Top off surface cmt plug. Erect DH marker.
- 15. Provide workorder to Buddy Shaw for surface reclamation.

Run 23

