	Forn (A)	<b>n 9-</b> 3 pril 19	31 b 52)	-
Ì				

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency	Vindov Book
********	

NOW Mavajo Tribal Losso No. 1-149-IND-8723

	X	SUBSEQUENT REPORT OF WATER SHUT-OFF
OTICE OF INTENTION TO DRILLOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
OTICE OF INTENTION TO CHANGE PLANS OTICE OF INTENTION TO TEST WATER SHUT-OFI		SUBSEQUENT REPORT OF ALTERING CASING.
OTICE OF INTENTION TO REDRILL OR REPAIR W	I	CURCOUTUT DEPORT OF PERRILLING OF PEPAIR
OTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMER ECELYET
OTICE OF INTENTION TO PULL OR ALTER CASIN	ıG	SUPPLEMENTARY WELL HISTORY WAY 2 3 1956
OTICE OF INTENTION TO ABANDON WELL		
		U.S. GEOLOGICAL ZUR
(INDICATE ABOVE BY	CHECK MARK NAT	TURE OF REPORT, NOTICE, OR OTHER PARMINGTON, NEW ME
		<b>Ney 22</b> , 19_5
Nevajo		(N)
ll No is located 660	ft. from	${\mathbb{N} \atop \mathbb{R}}$ line and 1960 ft. from ${\mathbb{N} \atop \mathbb{W}}$ line of sec. 25
		n ma
(1/4 Sec. and Sec. No.) (Tr	vp.) (I	Range) (Meridian)
	en Juan	New Mexico
(Field)	(County or 8	Subdivision) (State or Territory)
e elevation of the derrick floor ab	ove sea level	is 7464 it.
	DETAILS	s of work
	DETAILS	s of work
	DETAILS	
ate names of and expected depths to objective s ing po	DETAILS sands; show sizes, oints, and all other	s of work
ate names of and expected depths to objective s ing po	DETAILS sands; show sizes, oints, and all other	S OF WORK  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)
ate names of and expected depths to objective sing portion of the commence at once & drill to set approx 175° 13 3/8°	DETAILS sands; show sizes, oints, and all other	s of work
To commence at once & drill to set approx 175' 13 3/8"	DETAILS sands; show sizes, oints, and all other to 7000° casing an	S OF WORK  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test
To commence at once & drill for set approx 175° 13 3/8° for water shirt off. To set approx 2200° 8 5/8°	DETAILS sands; show sizes, oints, and all other to 7000° casing an	S OF WORK  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)
To commence at once & drill for set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks.	DETAILS sands; show sizes, oints, and all other  to 7000' casing an casing &	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill fo set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks.	DETAILS sands; show sizes, oints, and all other  to 7000' casing an casing &	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To comence at once & drill fo set approx 175' 13 3/8" for water shirt off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He	DETAILS sands; show sizes, oints, and all other casing an casing a surnosa FM sing and o	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill To set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He	DETAILS sands; show sizes, oints, and all other casing an casing a surnosa FM sing and o	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill To set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He	DETAILS sands; show sizes, oints, and all other casing an casing a surnosa FM sing and o	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill To set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He	DETAILS sands; show sizes, oints, and all other casing an casing a surnosa FM sing and o	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill to set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He to set approx 7000' 52" can and to perforate and complete	DETAILS sands; show sizes, oints, and all other leteral control of the control of	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.
To commence at once & drill to set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He to set approx 7000' 52" can and to perforate and complete	DETAILS sands; show sizes, oints, and all other leteral control of the control of	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.
To commence at once & drill fo set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He for set approx 7000' 51" can and to perforate and complete the comple	DETAILS sands; show sizes, oints, and all other leteral control of the control of	s of work  weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.
To commence at once & drill to set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He To set approx 7000' 5% can and to perforate and sample	DETAILS sands; show sizes, oints, and all other leteral control of the control of	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate ownert to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.
To comence at once & drill to set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He to set approx 7000' 5%" cannot be perforate and complete the company	DETAILS sands; show sizes, oints, and all other leteral control of the control of	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate ownert to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.
To comence at once & drill to set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He for set approx 7000' 5% can and to perforate and complete	DETAILS sands; show sizes, oints, and all other leteral control of the control of	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate ownert to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.
To comence at once & drill to set approx 175' 13 3/8" for water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He for set approx 7000' 5% can and to perforate and complete the perforate and complete the perforation of work must recompany M. M. Garrett delicated and d	DETAILS sands; show sizes, oints, and all other  to 7000' casing an casing a surmosa FM sing and contents sing and contents sive approval in w	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  desiroulate coment to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  Hement with 3-400 sacks, to test for leaventional manner.
To commence at once & drill to set approx 175' 13 3/8" For water shut off. To set approx 2200' 8 5/8" off or leaks. To core and DST somes in He to set approx 7000' 52" cannot be perforate and complete to perforate and complete to perforate and complete to the perforate and th	DETAILS sands; show sizes, oints, and all other  to 7000' casing an casing a surmosa FM sing and contents sing and contents sive approval in w	weights, and lengths of proposed casings; indicate mudding jobs, cemer important proposed work)  d circulate ownert to surface & test  coment with 200 sacks, test for shut  between 6000'-6900'.  coment with 3-400 sacks, to test for leaventional manner.

RECEIVED

PITCS WAS CATACO MONOCOS B COLORIOS DE CO

the second of the second of the second

.

- (restable-6)