State of New Mexico : Submit 3 Copies Form C-10 Energy, Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-19 DISTRICT] P.O. Box 1980, 110664, 1981 \$8240 OIL CONSERVATION DIVISION WELL AT NO. P.O. Box 2088 30 *045 07* 949 DISTRICT II P.O. Drawer DP, Anteria, NW 11210 Santa Fe, New Mexico 87504-2088 S. Indicate Type of Lease 2LYLE | FEE (DISTRICT III 1000 Rio Diracor Rd., Assec, NW 87410 6 State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS [DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Leave Haine or Unit Agreement Name DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS) Likens Gas Com "B" 1. Type of Well: well] WELL 3 OTHER 2. Name of Operator 1. Well No. 1 Attn: John Hampton Amoco Production Company 1. Address of Operator 9. Pool name or Wildest P.O. Box 800, Denver, Colorado 80201 Aztec Pictured Cliffs 4. Well Location _:_790 790 South East _ Feet From The Feet From The 29N 10W San Juan Section Township Range MIMI County 10. Elevation (Show whether DF, RXD, RT, GR. 11c.) 5525' GL Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT DOB OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all personal details, and give personal datas, including environted date of starting any proposed world SEE RULE 1103. Amoco Production Company intends to plug and Abandon the subject well. See attached for procedure: MAY2 8 1992 OIL CON. DIV. DIST. 3 muz Sr. Staff Admin. Supv. 5/18/92 TYTE ON PROT HAME <u>John Hampton</u> (This opeca for State Use) Original Signed by CHARLES GHOLSON DEPUTY OIL & GAS INSPECTOR, DIST.

ארצוים של אווארואאלי אוואנואליים אווא

Lickins Gas Com B #1 PXA Procedures

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with water. NDWH. NUBOP.
- 3. POOH with 1 1/4" tbg. RIH with tbg and cement retainer. Set retainer at 1880'. Establish rate into perforations at 1910' to 1936'. Squeeze perforations with 30 sx class B cement. Pull out of retainer and spot a cement plug to 1800' (17 sx).
- 4. Run free point.
- 5. Cut and pull casing 50' above free point.
- 6. Set a continuous cement plug from free point surface. (est. 529 sx)
- 7. NDBOPE. Cut off casing and wellhead. Install PXA maker according to BLM.
- 8. Turn over to John Schwartz for reclamation.
- 9. Rehabilitate location according to BLM or state requirement.

BLM 92 KAY 20 PH 2: 22 019 FARILLIGTON, N.M.

LIKINS GC B # 1 LOCATION, P24 29N 10W SINGLE PC ORIGINAL COMPLETION 04/56 LAST FILE UPDATE 10/91 BY CSW

