

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	1
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Melborne Petroleum Corporation	8. Farm or Lease Name R.L. Finch
3. Address of Operator Bedford, Inc. Agent for & State of New Mexico	9. Well No. 1
4. Location of Well P.O. Box E, Farmington, New Mexico 87401	10. Field and Pool, or Wildcat Antic - PC
UNIT LETTER <u>B</u> <u>500</u> FEET FROM THE <u>N</u> LINE AND <u>1800</u> FEET FROM THE <u>E</u> LINE, SECTION <u>22</u> TOWNSHIP <u>29N</u> RANGE <u>11 W</u> NMPM.	12. County San Juan
15. Elevation (Show whether DF, RT, GR, etc.)	


### Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Oil Conservation Division has employed Bedford, Inc. to plug and abandon this well as follows:

- Clean out cement plug inside 5½" casing to 150'. Tag cement top @ 590'. If no bottom plug found, set cement plug from 620 to 500'.
- Set cement plug from 400' to 300' inside & outside 5½" casing.
- Set cement plug from 150' to 50', inside & outside 5½" casing.
- Set surface plug w/P & A Marker.
- Clean & restore surface.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Larry A. Bedford</u>	TITLE <u>Agent for State</u>	DATE <u>8-13-78</u>
APPROVED BY <u>AK Kendrick</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		