	1				3 OCC	_	-E 620					_				
NUMBER OF CO				3			e He	rd								
SANTA FE	DISTRIBUTIO	×/	<u> </u>		1 Chr											1
FILE U.5.G.S.		<i>j</i>	+-		I FII	M EW	MEXI	CO O	IL C	ONSER	HOITAY	COM	MOISSIN		FORM C-1 (Rev 3-55)	03
LAND OFFICE	OIL		-}			м	ISCEL	IAN	IFOU	SREP	ORTS O	N WE	F1 1 C		(164 3-33)	
TRANSPORTER PROBATION OF	GAS FICE		+-			-	IJCEL		LUU	JILLI		14 W.				
PERATOR				i	(Sub	mit to	approp	riate l	Distric	t Office	as per Co	nmissi	ion Rule 1	106))	
Name of Com	pany				« 		v ···	·	Addres	ss						
Redfe		Herd	In	3.					Bo	x 1747	, Midlar	id, T	exas			
Lease						Well	No.		_		Township		R	ange	124	
Date Work Pe				Pool		Д	1		<u> </u>	8	291	X				
9-15-61		29-6		P 001	Basir	Dal	kota			ľ	County Sar	Jua	n /0	FI'	FI//CV	
								OF: (Check	appropria	te block)		- / M	LU	FIA FR	
Beginnii	ng Drilli	ng Ope	ration	s		Casing	Test an	d Cem	ent Job		Other (1	Explair	n):	CC 1	E 10641	
Pluggin	g .				F	Remed	ial Work						ן ע		1 5 196 1	
Detailed acco	unt of v	ork do	ne, na	ture a	d quantit	y of m	aterials	used,	and res	ults obtai	ned.				ON. COM.	
			,					-,					/	D!	ST. 3	
Spud 9 s	ama (n 9-	15-6	1.	rilled	יוו ו	hole	to:	2351.	Ran '	7 joints	of	8 5/8"	0.D	J-55 24#	
															. POB 8 a.	m.
															o.k. T.D.	
															og; direc-	
															sks weight	1
meterda:	Log an		~4 ~~	d	nd what d		E D'	7764	~wo.4 ≁mR ~	of hold	o Don	gahl	Impana	- 44	irectional	
															185 joints	- 1
Told - m	AC A	: # T	C. C.	9 27 9 7 4 70 4	CORPA	001	er ore	dan.	# # #OT##	FUJO	EO -at		The TA		mented	
42 0.D.	TO.		77 , (o ra	, STOU	. Ure	RT CSS	ing.	هو ذ	. 0 020	. D Bet	at c	מאת טבטי	, 6		
								_ = .								ı
MIST TO) 58 9 2	3 57	gel	, 50	sacks	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61.	. uc	MOG MICH	reu	erns while	
cementi:	18 → 1) Sagn	ecip	roca roca	, 50 ted	sacks	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61. a xi mum (em e r	ting pr	es s :	arns while are 1100 ps	1 -
cementi	1g - 1	ecip	roca	ted	sacks sasing	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61. aximm	. uc	ting pr	esa	are 1100 pa	1 -
cementi: Released	1g - 1	ecip	roca	ted	sacks sasing	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61. aximm	. GC Cem a r	ting pr	es s t	are 1100 pa	1 -
cementi	1g - 1	ecip	roca	ted	sacks sasing	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61. a xi mm	em e r	iting pr	Per Per	are 1100 pa	1 -
cementi	1g - 1	ecip	roca	ted	sacks sasing	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61. a xi mum (. uc cemen	ting pr	es a	are 1100 pa	1 -
cementi	1g - 1	ecip	roca	ted	sacks sasing	Nea'	t - PO	B 7:	15 p.	m. on	9-29-61.	semen	iting pr	POU	are 1100 ps	1 -
Released	lg → l	recip 11 p	roca	ted	sacks sasing	Nea:	t - PO while)B 7:	15 p.	m. on ng. M	aximum (cem a r	nting pr	esa	are 1100 pa	4 -
Released	1g - 1	recip 11 p	roca	ted 9=29	sacks masing -61.	Nea:	t - PO while Position Engi	B 7:	15 p. menti	m. on ng. M	aximum (Redfe	ating pr	esa	are 1100 pa	1 -
Released	lg → l	recip 11 p	roca	ted 9=29	sacks masing -61.	Nea:	e vhil	B 7:	15 p. menti	m. on ng. M	aximum (Redfe	nting pr	esa	are 1100 pa	1 -
Released	lg → l	recip 11 p	roca	ted 9=29	sacks masing -61.	Nea:	e vhil	neer	15 p. menti	m. on ng. M	Company PORTS O	Redfo	ating pr	essa	Inc.	1 -
Released by	lg → l	recip 11 p	roca:	ted 9=29	sacks masing -61.	Nea:	e PO Position Engi FOR R ORIGI	neer	15 p. menti	m. on ng. M	aximum (Redfo	ating pr	essa	are 1100 pa	1 -
Released by	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks masing -61.	Nea:	e PO Position Engi FOR R ORIGI	Deer	15 p. menti	m. on ng. M	Company PORTS Of	Redfo	ating pr	ess.	Inc.	1 -
Witnessed by T. A. D F Elev. Tubing Diame	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks sasing -61.	Nea:	e PO Position Engi FOR R ORIGI	Deer	15 p. menti	ng. M	Company PORTS Of	Redfo	orn & He	ess.	Inc.	11 -
Witnessed by D F Elev.	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks sasing -61.	Nea:	e PO Position Engi FOR R ORIGI	Deer	15 p. menti	ng. M	Company PORTS Of	Redfo	orn & He	ess.	Inc.	11 -
Witnessed by T. A. D F Elev. Tubing Diame	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks sasing -61.	Nea:	e PO Position Engi FOR R ORIGI	Deer EMED	DIAL WELL D	ng. M	Company PORTS Of	Redfo	orn & He	ess.	Inc.	11 -
Witnessed by T. A. D F Elev. Tubing Diame	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks sasing -61.	Nea:	e PO Position Engi FOR R ORIGI	Deer EMED	DIAL WELL D	ng. M	Company PORTS Of	Redfo	orn & He	ess.	Inc.	11 -
Witnessed by T. A. D F Elev. Tubing Diame	ng - 1 l rig	recip 11 p	roca:	ted 9-29	sacks sasing -61.	Nea: o.k	osition Engi FOR R ORIGI	B 7: B CC	DIAL WELL D	ORK REDATA	Company PORTS Of	Redfo	orn & He	ess.	Inc.	11 -
Witnessed by T. A. D F Elev. Tubing Diame	Duge	un	roca:	ted 9-29	sacks basing -61.	Neat o.k	cosition Engi FOR R ORIGI PBTE	Deer EMEDINAL TO	DIAL WELL DOIL Strin	ORK REDATA	Company PORTS Of Producing er tion(s)	Redfo	orn & He	Com	Inc.	
Witnessed by T. A. D F Elev. Tubing Diame	Duge	n n n n n n n n n n n n n n n n n n n	roca:	ted 9-29	sacks basing -61. LL IN BI	Neat o.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL W	ORK REDATA Ing Diamet OVER Water P	Producing Producing tion(s)	Redfe	orn & He	rd,	Inc. Pletion Date Gas Well Poten	
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int	Duge	un	roca:	ted 9-29	sacks basing -61.	Nea* O.k	Position Engi FOR R ORIGI PBTD	Deer EMEDINAL TO	DIAL W	ORK REDATA Ing Diamet OVER Water P	Company PORTS Of Producing er tion(s)	Redfe	orn & He	rd,	Inc.	
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int	Duge	n n n n n n n n n n n n n n n n n n n	roca:	ted 9-29	sacks basing -61. LL IN BI	Nea* O.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL W	ORK REDATA Ing Diamet OVER Water P	Producing Producing tion(s)	Redfe	orn & He	rd,	Inc. Pletion Date Gas Well Poten	
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After	Duge	n n n n n n n n n n n n n n n n n n n	roca:	ted 9-29	sacks basing -61. LL IN BI	Nea* O.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL W	ORK REDATA Ing Diamet OVER Water P	Producing Producing tion(s)	Redfe	orn & He	rd,	Inc. Pletion Date Gas Well Poten	
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover	Duge	n n n n n n n n n n n n n n n n n n n	roca:	ted 9-29	sacks basing -61. LL IN BI	Nea* O.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL W	ORK REDATA ORK REDATA OVER Water P	Producing Producing	Redfe	orn & He al Oil String I	rd,	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After	Duge	ate of Test	T D	FI Tubin	Producti BPD	Nea: O.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL WELL DOIL String	ORK REDATA OVER Water P	Producing Producing tion(s)	Redfe	orn & He al Oil String I	rd,	Inc. Pletion Date Gas Well Poten	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After	Dugeter erval(s)	ate of Test	T D	FI Tubin Oil	Producti BPD	Nea: O.k	Position Engi FOR R ORIGI PBTD	neer EMED	DIAL WELL DOIL String	ORK REDATA OVER Water P	Producing Producing	Redfe	orn & He al Oil String I	rd,	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After Workover	Duge ter erval(s) erval	ate of Test	T D RVAT Sign	FI Tubin	Producti BPD	Nea: O.k	Position Engi FOR R ORIGI PBTD	DE 7: DE CE	DIAL WELL DOIL String	ORK REDATA OVER Water P B by certify best of n	Producing Producing Producing tion(s) that the inny knowled	Cub	GOR of feet/Bbl	Com Depth	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After	Duge ter erval(s) OIL Or A	ate of Test CONSI	T D ERVAT Sign (END	FI Tubin Oil	Producti BPD	Nea: O.k	Position Engi FOR R ORIGI PBTD	DE 7: DE CE	DIAL WELL DOIL String	ORK REDATA OVER Water P B by certify best of n	Producing Producing Producing tion(s) that the inny knowled	Cub	GOR of feet/Bbl	Com Depth	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After Workover	Duge ter erval(s) OIL Or A.	ate of Test CONSI	T D ERVAT Sign (END	Tubin Oil PRIC	Producti BPD	O.k	Position Engi FOR R ORIGI PBTD Gas F	DE 7: DE CE	DIAL WELL DOIL String	ng. Mang Diamet OORK RE OATA OVER Water P B obstricting best of re- riginal s	Producing Producing Producing tion(s) that the inny knowled	Cub	orn & He al Oil String I	Com Depth	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After Workover	Duge ter erval(s) OIL Or A.	ate of Test CONSI	T D ERVAT Sign (END	Tubin Oil PRIC	Producti BPD	O.k	Position Engi FOR R ORIGI PBTD Gas F	DE 7: DE CE	Produci WORK	ORK REDATA ON TO THE PROPERTY OF THE PROPERTY	Producing Producing er tion(s) that the inny knowled signed by	Cub	GOR of feet/Bbl	Com Depth	Inc. Pletion Date Gas Well Potent MCFPD	ial
Witnessed by T. A. D F Elev. Tubing Diame Perforated Int Open Hole Int Test Before Workover After Workover	Duge ter erval(s) OIL Or A.	consignal R. I	T D ERVAT Sign (END	Tubin Oil ORIC REG E	Producti BPD	O.k	Position Engi FOR R ORIGI PBTD Gas F	DE 7: DE CE	Produci WORK	ORK REDATA ON BOOK REDATA	Producing Producing Producing tion(s) that the inny knowled	Cub	GOR of feet/Bbl	Com Depth	Inc. Pletion Date Gas Well Potent MCFPD	ial