

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE	1	
FILE	1	
U.S.G.S.		
LAND OFFICE		
OPERATOR	1	

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Pettus and Associates	8. Farm or Lease Name Don Stock
3. Address of Operator P. O. Box 234, Farmington, New Mexico 87401	9. Well No. 1
4. Location of Well UNIT LETTER <u>E</u> , <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>29N</u> RANGE <u>16W</u> NMPM.	10. Field and Pool, or Wildcat Jewett Valley Gal.
15. Elevation (Show whether DF, RT, GR, etc.) 5102' GR	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spot 20 sacks bottom plug 3542-3200', pull tubing (hole at 1209'), work and shoot 5½" casing at 1030', pull and lay down casing, run tubing to 1800' and spot 33 sacks, pull tubing to 1209' and spot 50 sacks, pull tubing to 1030' and spot 50 sacks, pull tubing and squeeze cement, cut 8-5/8" casing loose from 13-3/8" casing, shoot 8-5/8" casing at 790' and pull, hung up, lost 4 joints, spot 25 sacks plug at 790', spot 60 sacks at 300', 10 sacks surface and marker.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Original signed by T. A. Dugan TITLE Agent DATE 12-27-73
Thomas A. Dugan

APPROVED BY Emory C. Ames TITLE _____ DATE 5-31-74

CONDITIONS OF APPROVAL, IF ANY: