State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and Re	polon on wolls	
		API	# (assigned by OCD)
. Type of Well		5.	Lease Number
GAS			Fee
		6.	State Oil&Gas Lease #
Name of Operator		7.	Lease Name/Unit Name
RESOURCES ALL	& GAS COMPANY		Kattler
011	8. Well No.		
. Address & Phone No. of Opera	tor		1
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	Pool Name or Wildcat Fulcher Kutz Pict.Cli
. Location of Well, Footage, S		Elevation:	
990'FNL, 1650'FWL, Sec.2, T-	29-N, R-12-W, NMPM, San	Juan County	
Type of Submission	Type of Act		
X Notice of Intent	Abandonment	_ Change of Pl	
Godina and the Daniel	Recompletion	_ New Construc	
Subsequent Report	Plugging Back Casing Repair	_ Non-Routine Water Shut o	_
Final Abandonment	Altering Casing	_ water shad to Conversion t	
	X Other - Restimulat	_	,
It is intended to restimu	leted Operations		the subject well
It is intended to restimution the following of Pull 1" tubing. Confoam fracture trees.	leted Operations	formation of	050'. Acidize and
It is intended to restimuting the following of the Pull 1" tubing. C	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of	050'. Acidize and and return well
It is intended to restimuting the following of the Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 20 one. Clean out	050'. Acidize and and return well
It is intended to restimuting the following of the Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 20 one. Clean out	050'. Acidize and and return well
It is intended to restimuting the following of the Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 20 one. Clean out	050'. Acidize and and return well
It is intended to restimution the following of Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 2 one. Clean out	050'. Acidize and and return well
It is intended to restimution the following of Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 2 one. Clean out	050'. Acidize and and return well
It is intended to restimuting the following of the Pull 1" tubing. Confoam fracture trees.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 2 one. Clean out	O50'. Acidize and and return well CCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCCC
It is intended to restimuting the following of the Pull 1" tubing. Confoam fracture treaton production.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to at the Pictured Cliffs zo	formation of tal depth at 2 one. Clean out	OSCAL DELANGED
It is intended to restimution the following of the Pull 1" tubing. Confoam fracture treato production.	pleted Operations late the Pictured Cliffs manner: lean out to plug back to	formation of tal depth at 2 one. Clean out	OSCAL DELANGED

Kattler #1 **Pertinent Data Sheet**

API#: 300450884400

Location: 990 'FNL & 1650 'FWL, Unit C, Section 2, T29N, R12W, San Juan County, New Mexico

Latitude: 36° - 45.54'

Longitude: 108° - 4.24'

Field: Fulcher Kutz PC

Elevation: 5855 'GL

TD: 2060 '

5865 'KB

PBTD: 2050 '

DP #: 38572

Spud Date: 1/26/45

Compl Date: 3/9/45 Lease: SRC 0020254 (Private)

GWI: 25 %

Initial Potential: 1750 Mcfd

NRI: 21.875 % Prop#: 20254

Original SIP: 513 psi

Casing Record:

Hole Size (ln.)	Csq Size (In.)	Wt. (#'s) & Grade	Depth Set (Ft.)	Cement (Sx.)	Cement (Top)
18	15 1/2	60 ?	47	?	?
8	5 1/2	14 J-55	1,960	50	1683' @ 75% eff.
4 3/4	3 1/2	7.7 J-55	2,050	205	Surf @ 75% eff.

Tubing Record:

Joints Comments Depth Set Tbq. Size Wt. & Grade 1,974 94 1.7 Line Pipe

Formation Tops:

Ojo Alamo:

595

All Tops are Estimated

Kirtland Shale: 709'

Fruitland:

1,741 Pictured Cliffs: 1,954'

Logging Record:

IES

Original Stimulation: Original: Natural gauge: 1400 Mcfd, SOH w/ 40 qts SNG, Restim: Perfd 1961-71', 1991-95',

2002-07' w/ 2 SPF, SWF w/ 18,900 gal wtr, 10,000# 20/40, and 10,000# 10/20 sd, Post WO

gauge: 356 Mcfd, SIP 214

Workover History:

5/15/67: 3-1/2 Restim (see above Stimulation)

Production History: 7/97 PC capacity: 15 MCF/D. 7/97 PC cum: 879 MMCF.

Pipeline:

WFS

Filfe: Q: area !pcteam 1998 welldata restim RSTMPERT.DOC

Kattler #1

Section 2 C, T-29 -N R-12 -W San Juan, New Mexico

Fulcher Kutz Pictured Cliffs Field Wellbore Schematic

