Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

NOG 8707-1145

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals	Navajo	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation N/A	
1. Type of Well X Oil	8. Well Name and No. Rattlesnake 202 9. API Well No.	
P.O. Box 612007 Dallas, TX 75261-2007 753-6900	30-045-21067 10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description) Section 2-29N-19W 2000' FNL & 330' FEL	Rattlesnake 11. County or Parish, State San Juan, NM	
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION		
Notice of Intent X Notice of Intent D E G E W E W E N Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other Other Other Other Other Casing Notice Other Othe	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well	
ම්බන්ත ව	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Please be advised Harken Southwest plans to plug and abandoned the subject well by September 5, 1997. The subject well will be permanently abandoned utilizing the following procedures:


- 1. MIRU, remove 4-1/2" rector head and line valves
- PU serrated collar & RIH w/2-3/8" work string. Tag CIBP @ 790' 2.
- Mix up Class "B" cmt & circ cmt to EOT. Pump cmt while pulling out of hole. Fill open hole from CIBP @ 790' to surface w/146 sxs.
- 5. Cut off csg 4' below surface. Fill annulus from 17' to surface..
- RDMO. Weld on regulation surface marker, cut anchors.

Harken will notify the BLM 48 hours prior to starting abandonment operations. In addition, attached for your reference is the current wellbore diagram and the proposed plugged wellbore diagram.

Approved by Conditions of approval, if any:	Date JUN - 6 1997
Signed Autilia Hard Correct Production Administrator	Date 5/27/97
cc:	Navajo Nation BIA - Gallup, NM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

HARKEN SOUTHWEST CORPORATION



TD 790'

PBTD = ?

HARKEN SOUTHWEST CORPORATION

(Jormerly Chuska Energy Company)

Surface P & A marker

Rattlesnake # 202 2000' FNL, 330' FEL, Sec 2, T29N, R19W San Juan County, New Mexico

Plug and Abandonment Configuration

7", 22# casing set @ 17.5' w 3 sacks

Total calculated cement TD to surface: 146 sacks

6 1/8" hole for 4 1/2" csg

4 1/2", 9.5# casing appears to have been removed

Dakota 'A' Top @ 780'

TD 790'

PBTD = ?