

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1170' FNL, 1100' FEL, Sec.28, T-29-N, R-9-W, NMPM

5. Lease Number
NMNM03999

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Grambling #8

9. API Well No.
30-045-21564

10. Field and Pool
Blanco Pict'd Cliffs

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

It is intended to add pay to the Pictured Cliffs formation and repair the bradenhead in the subject well according to the attached procedure and wellbore diagram.

14. I hereby certify that the foregoing is true and correct.

Signed

[Signature]

Title Regulatory Supervisor Date 8/26/02

TLW

(This space for Federal or State Office use)

APPROVED BY */s/ Joe Hewitt*

Title ACTING

Date

AUG 30

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Grambling #8 Sundry Notice

1170' N, 1100' E

A - 28 - 29N - 09W

San Juan County, NM

1. Run CBL.
2. Pressure test casing to 4500#.
3. Selectively add perforations within the Pictured Cliffs formation.
4. Fracture stimulate the Pictured Cliffs formation.
5. Set composite bridge plug 50' above top PC perforation.
6. Perforate 2 squeeze holes according to CBL (step 1) to remediate bradenhead failure.
7. Establish circulation. Cement annular volume, circulating Class B neat with 2% CaCl_2 cement to surface. Cement required dependent on CBL (step 1).
8. Drill out cement and composite bridge plug. Clean out well and return to production.


Grambling #8

Section 28A, T-29-N, R-09-W
San Juan County, New Mexico
Blanco PC Field
Lat 36° 42.04', Long 107° 46.75'
GL: 5705' KB: 5717'

CURRENT

PROPOSED

8-5/8" csg set @ 123'
Cmt'd w/112 cu ft
Circ to surface



Top of Ojo @ 1008'

Top of PC @ 2120'

2-7/8", 6.4#, J-55 csg
Set at 2290'
Cmt w/392 cu ft


TOC @ 750' T.S.

Pictured Cliffs perfed at 2134' -
40', 2170' - 74' 6 spz
Water frac'd w/ 26,500 gal
water, 26,000# 20/40 sd.

PBTD @ 2280'

TD @ 2290'

Sqz holes perfed at xxxx'
Sqz'd with xx sxs Class B
cement



Pictured Cliffs: add
perforations and
fracture stimulate with
95Q ClearFrac and
20,000# 12/20 sand