## ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES ACCEIVED			
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE	1		
OPERATOR			

	OIL CONSERVATION DIVISION		
DISTRIBUTION	P. O. BOX 2088	Form C-103	
SANTA FE	SANTA FE, NEW MEXICO 87501	Revised 19-1-78	
FILE		5a. Indicate Type of Lease	
U.S.G.S.	· ·		
LAND OFFICE			
OPERATOR		5. State Oil & Gas Lease No.	
S	UNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM TUSE **AF	UNDRY NOTICES AND REPORTS ON WELLS  FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  PPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
•		7. Unit Agreement Name	
OIL GAS X	7	The state of the s	
. Name of Operator	OTHER-		
Name of Operator		8. Farm or Lease Name	
El Paso Natural C	Sas Company	Hubbell	
. Address of Operator		9. Well No.	
P O Box 4289 Far	rmington, New Mexico 87499	#19	
Location of Well	mington; now morred of 435	10. Field and Pool, or Wildcat	
UNIT LETTER P	. 1125' FEET FROM THE South LINE AND 1180' FEET	Bloomfield Farmington	
East Line	SECTION 19 TOWNSHIP 29N RANGE 10W		
THECINE,	SECTION TOWNSHIP RANGE N	~~~. (	
mmmmm	15. Elevation (Show whether DF, RT, GR, etc.)	12, County	
<i>İППППППП</i>	5475' GR.	San Juan	
c. Ch	neck Appropriate Box To Indicate Nature of Notice, Report or	Other Data	
		ENT REPORT OF:	
NOTICE	or in Entrol to:	ENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING SPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB		
	OTHER		
OTHER			
7 Describe Stangard or Comple	eted Operations (Clearly state all pertinent details, and give pertinent dates, inclu	Ji	
work) SEE RULE 1103.	ered Operations (Crearly state are pertinent actairs, and give pertinent dates, inclu	aing estimated date of starting any proposed	
1)	Plug well. Non-productive.		
	Use 13 sacks to plug 540'-992' (from Ojo Alamo to	hase of Farmington s s )	
3)	Perf 4 holes @180'. Use 19 sx to fill annulus be	,	
3)		stween 124 note and	
	2 7/8" casing.		
4)	Use three sx to fill 2 7/8" to surf.		
5)	Use 9.0 - 9.2 mud between plugs.		
. 6)	Install dry hole marker.		
7)	Restore location.	•	
,,	Restore rocation.		
	in the second	DECEIVEM	
	D		
		עון וו	
	<b>.</b>	MAY 2 6 1983 ·	
		MAI 2 0 1000	
		OIL COM DIV	
	· · · · · · · · · · · · · · · · · · ·	OIL CON. DIV.	
		DIST. 3	
	•	were the comment	
8. I hereby certify that the information	mation above is true and complete to the best of my knowledge and belief.		
-	$\mathcal{Q}$		
11.00.	L. Co 4 Draduction Engineer	May 25 1007	
ICHED COLOR	Take Production Engineer	May 25, 1983	
1.1 من ي	y CHARLES GHOLSON CUPRIMISOR DISTRICT 模 3	mai 40 loo	
Original Signed by	A CHAUTER AND ALL AND	STATE OF THE STATE	