# 0-5 UNITED STATES

# DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT

Sundry Notices and Repor	755 87 W + 101 sk H 7: 3	5	
1. Type of Well GAS	070 FARMINGTON, N	6.	Lease Number SF-076958 If Indian, All. or Tribe Name
2. Name of Operator		7.	Unit Agreement Name
SOUTHLAND ROYALTY COMPANY			
		8.	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505)	326-9700	9.	Hare #22 API Well No. 30-045-23190
4. Location of Well, Footage, Sec., T, R, M 800'FSL, 1830'FWL, Sec.14, T-29-N, R-10-W,	10.	Field and Pool Aztec Pictured Cliffs/ Blanco Mesaverde	
		11.	County and State San Juan Co, NM
		, OTHER	DATA
		e of Pl	ans
Recomple	etion New Co	onstruc	tion
			<del>-</del>
Final Abandonment Altering	g Casing Conve		
13. Describe Proposed or Completed Operation	ons	<del></del>	· · · · · · · · · · · · · · · · · · ·
It is intended to repair the bradenhead	d on the subject w		
			GENVED MAY 1 7 1995
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA  Type of Submission  X Notice of Intent  Abandonment  Recompletion  Plugging Back  Non-Routine Fracturing  Casing Repair  Water Shut off  Altering Casing  Conversion to Injection  X Other - Bradenhead repair  Describe Proposed or Completed Operations  It is intended to repair the bradenhead on the subject well according to the procedure and wellbore diagram.  DECENOMENTAL AND ADDRESS OF THE PROPOSE OF THE PROPOS	COM. DIV. Dist. 3		
7 7 1 1 - 6 7			
Signed MAN July (LWD5) Titl	e <u>Regulatory Affai</u>	<u>rs</u> Da	te 5/9/95
(This space for Federal or State Office use) APPROVED BY Title		Date	
CONDITION OF APPROVAL, if any:			APPROVED

**NMOCD** 

MAY 1 0 1995 DISTRICT MANAGER

### WORKOVER PROCEDURE - BRADENHEAD REPAIR

#### **HARE #22**

Aztec Pictured Cliffs / Blanco Mesaverde Dual SW/4 Sec. 14, T29N, R10W San Juan Co., New Mexico DPNO 27256 (MV); 27257 (PC)

- 1. Comply to all NMOCD, BLM, and MOI regulations. Conduct daily safety meetings for all personnel on location.
- 2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Install a 400 bbl frac tank and an atmospheric blow tank. NU blooie line to blow pit, and relief line to atmospheric tank. Fill frac tank with 1% KCl water.
- 3. Blow down Pictured Cliffs tubing (65 jts, 1 1/4", 2.4 ppf, J55, EUE), and Mesaverde tubing (137 jts, 2 3/8", 4.7 ppf, J55, EUE) to atmospheric tank. Control well with 1% KCl water as needed. ND wellhead and NU BOP's. Test and record operation of BOP's. Send wellhead to A-1 Machine or WSI for inspection.
- 4. PU on Pictured Cliffs tubing and strap out of hole. Unseat Mesaverde tubing from PBR at 2195', and strap out of hole. Visually inspect tubing, and replace joints that are in bad condition. (Note any buildup of scale and notify Operations Engineer.) Send seal assembly to Baker for re-dress.
- 5. PU 6 1/4" bit, casing scraper (7", 20 ppf), and CO to top of 4 1/2" liner at 2191'. PU 7" retrievable BP and packer, and TIH. Set RBP at 1950'. Pressure test RBP and casing to 1000 psig. Spot two sacks of sand on top of RBP. (If casing does not pressure test, isolate failure and contact Operations Engineer.)
- 6. RU wireline unit. Run CBL (with 1000 psi) to determine TOC behind 7" casing. Estimated TOC is 1600' per temperature survey. Perforate 4 squeeze holes 20' above TOC.
- 7. TiH with 7" fullbore packer and set 150' above squeeze holes. Pressure up backside to 500 psig. Establish rate with bradenhead valve open. If circulation is established through bradenhead valve, circulate hole clean. Contact Operations Engineer for design of cement slurry.
- 8. Mix and pump cement with turbulent flow behind pipe. Displace cement to packer. Close bradenhead valve and squeeze cement into perforations. (Max squeeze pressure 1000 psi.) Maintain squeeze pressure and WOC 12 hours (overnite).
- 9. Release packer and POOH. TIH with 6 1/4" bit and drill out cement. Pressure test casing to 1000 psig. Test for bradenhead flow. Re-squeeze as necessary to hold pressure, and to stop bradenhead flow.
- 10. TIH with retrieving tool and retrieve RBP from 7" casing. POOH and LD RBP.
- 11. PU 3 7/8" bit and casing scraper (4 1/2", 11.6 ppf), and CO to PBTD with air. Blow well clean and gauge production. POOH.
- 12. TIH with Mesaverde production tubing (seating nipple and pump-out plug one joint off bottom). Land tubing at 4415' with PBR seal assembly landed at 2195'. TIH with Pictured Cliffs production tubing (seating nipple one joint off bottom), and land at 2080'. (Use tubing choke as needed.)

- 13. ND BOP's and NU wellhead. Pump plug from Mesaverde tubing. Obtain final gauges.
- 14. Release rig.

Recommend:

Operations Engineer

Approve:

Drilling Superintendent

Contacts:

Cement

Wireline

Operations Engineer

Halliburton

Blue Jet Larry Dillon 325-3575

325-5584

326-9714

## PERTINENT DATA SHEET

4/5/95

WELLNAME: Hare #22					DP NUMBER: PROP. NUMBER:	00	27256 (MV) / 27257 (PC) 0020373A (PC) 0019527 (MV)			
WELL TY	'PE:	8lanco Mesa Aztec Picture				ELEVATION:		373' 885'		
LOCATION: 800' FSL, 18 Sec, 14, T29 San Juan Co		1			INITIAL POTENTIAL: INITIAL SITP: CURRENT SITP:		AOF	MV 1379 5/31/79 734 5/24/79 386 11/12/91	PC 3273 5/25/79 499 5/31/79 322 9/8/83	
OWNERS	HIP:	GWI: NRI: SJBT:	23.4221%	PC 17.1752% 15.1150% 37.4578%		DRILLING:	CON	UD DATE: MPLETED: L DEPTH: PBTD:	3/5/79 5/17/79 4711' 4671'	
CASING RE	CORD:	<del></del>				· · · · · · · · · · · · · · · · · · ·			-	<del></del> .
HOLE S	IZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CEI	MENT		тос
12 1/4	••	9 5/8"	36#	K55	231'		110 sx			Circ to s
8 3/4"		7"	20#	K55	2348'		220 sx		TS	1600
6 1/4"		4 1/2"	10.5#	K55	4711'	Liner hanger @ 2191'	340 sx		Calc.	2191
Tubing	(MV) (PC)	2 3/8" 1 1/4"	4.7# 2.4#	J55 J55	4397' 2195'	137 Jts. EUE J55 8 Rd 65 Jts. J55, 8 Rd. PBR set @ 2195'.	d 			
FORMATION	TOPS:	Ojo Alamo Kirtland Fruitland Pictured Cliffs Lewis Huerfanito Be Chacra		1016' 1742' 2046'	·	Cliff House Menefee Point Lookout Mesa Verde Gallup Graneros Dakota		3685' ·		
LOGGIN	G:	IES, GR Dens	sity, GR-Ind., GR	Correlation, Cl	BL					
PERFORAT	TIONS	PC MV	2046', 2052', 20 3891', 3900', 39 (Total of 16 hole	08', 4103', 4101	0', 2078'. ( 8', 4124', 4	Total of 6 holes) 132', 4314', 4324', 4340', 4354	4', 4362', 43	70', 4393', 4	1407', 4416'.	
STIMULATION: PC 114,000# 20/40 sand, 124,000 gal. water MV 57,000# 20/40 sand, 62,000 gal water										
WORKOVER H	ISTORY:	None.								
PRODUCTION F	d <b>e</b>	Gas	Qii			DATE OF LAST PRODUCTION:		Gas	Qil	
Cumulative a	Current:	419.7 MMcf 1.7 MMcf	2.2 bo 0 bo			1- 95	MV 1	.7 MMcf	0 bo	
FICTORE C	s of 1995	275 MMcf	0 bo			1- 95	PC 9	973 Mcf	0 bo	
Cumulative a	Current:	973 Mcf	0 bo							

### Hare 22

Current -- 3/2/95

Blanco Mesaverde / Aztec Pictured Cliffs DPNO: 27256 / 27257 RECEIVED BLM

800 FSL, 1830' FWL Sec. 14, T29N, R10W, San Juan Co., NM 95 MAY 10 AM 7: 35

4 1/2", 10.5#, K55 Liner set @ 4711'.

Cmt. w/ 340 sx.

Spud: 03-05-79

Completed: 05-17-79


Ojo Alamo @ 1016

Fruitland @ 1742

Pictured Cliffs @ 2046

Cliff House @ 3685'

Point Lookout @ 4308'



PBTD @ 4671'