

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

## OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Pioneer Production Corp.		8. Farm or Lease Name Hartman
3. Address of Operator P O Box 208, Farmington, NM 87499		9. Well No. 1E
4. Location of Well UNIT LETTER <u>F</u> <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>1990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>31</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.		10. Field and Pool, or Wildcat Basin Dakota/Otero Chacra
15. Elevation (Show whether DF, RT, GR, etc.) 5396' GL		12. County San Juan

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

## SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Dakota</u> <u>Abandonment</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

The Dakota was plugged and abandoned as follows:

1. Removed RBP's at 2600' and 4000'.
2. Set CIBP at 5900'. Dumped 3 sx cement on top. (50' plug).
3. Spotted 150' cement plug (10 sx) from 4050' to 4200'.
4. Spotted 150' cement plug (10 sx) from 3020' - 2870'.
5. Set CIBP at 2600'.

The Dakota plugged and abandoned as of 4-18-85. Chacra perms open to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jim L. Jacobs Jim L. Jacobs TITLE Agent DATE 4-25-85

Original Signed by CHARLES GNOLSON

APPROVED BY

DEPUTY OIL &amp; GAS INSPECTOR, DIST. #3

DATE APR 26 1985

CONDITIONS OF APPROVAL, IF ANY: