UNITED STATES DEPARTMENT OF THE INTERIOR

	ices and Reports on Wells 2	. No. 2 Th. 200 Th. 3 Th. 10 T	
	070 500	[][()], 5	Lease Number SF-076958
Type of Well	(S 10 9 1/7)	6.	If Indian, All.
GAS		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Tribe Name
	FEB 2000		
	RECEIVED)	Unit Agreement Na
Name of Operator	OIL CON. DIV		
BURLINGTON RESOURCES		7.	
1423CCRCLS OIL	& GAS COMPANY		Mall Name C Nomb
Address & Phone No. of Opera	tor	8.	Well Name & Number
PO Box 4289, Farmington, NM		9.	API Well No.
			30-045-24833
Location of Well, Footage, S		10.	Field and Pool
1810'FNL, 1840'FWL, Sec.15,	T-29-N, R-10-W, NMPM		Basin DK/Blanco N
		11.	County and State San Juan Co, NM
			Juli Julii Co, III
	DICATE NATURE OF NOTICE, REPO	RT, OTHER	DATA
Type of Submission	Type of Action		
Notice of Intent	Abandonment Cha	nge of Pl	
	Dogomalation May		
		Construc	
X Subsequent Report	Plugging Back Non	-Routine	Fracturing
	Plugging Back Non	-Routine er Shut o	Fracturing ff
X_ Subsequent Report	Plugging Back Non Casing Repair Wat	-Routine er Shut o	Fracturing ff
X_ Subsequent Report Final Abandonment	Plugging Back Non Casing Repair Wat Altering Casing Con X Other -	-Routine er Shut o	Fracturing ff
X_ Subsequent Report Final Abandonment	Plugging Back Non Casing Repair Wat Altering Casing Con X Other -	-Routine er Shut o	Fracturing ff
X_ Subsequent Report Final Abandonment Describe Proposed or Comp	Plugging Back Non Casing Repair Wat Altering Casing Con X Other -	er Shut o	Fracturing ff o Injection
X_ Subsequent Report Final Abandonment Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Cleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Lldn't rls. SDON.	er Shut on the ser shut of the service to the servi	Fracturing ff o Injection ls Otis perma-
X_ Subsequent Report Final Abandonment Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Aldn't rls. SDON. The point to top of pkr @ 4674	er Shut of exercision to exercise to rempt to refer to refer to the exercise t	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH,
X_ Subsequent Report Final Abandonment Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Aldn't rls. SDON. See point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1	er Shut of the service of the servic	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON.
X_ Subsequent Report Final Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Aldn't rls. SDON. See point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & p	er Shut of the ser Shut of the ser Shut of the series of t	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools
X_ Subsequent Report Final Abandonment Final Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. ee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & p bit, tag up @ 6702'. Est circ	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
X_ Subsequent Report Final Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Cleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att. Idn't rls. SDON. See point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & pbit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
X_ Subsequent ReportFinal Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/ 12-30-99 TOOH w/bit. TIH	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Cleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att. Idn't rls. SDON. See point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & pbit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. Hee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & phit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released.	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
X_ Subsequent ReportFinal Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/ 12-30-99 TOOH w/bit. TIH	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. Hee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & phit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released.	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. Hee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & phit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released.	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. Hee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & phit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released.	empt to r '; 100% f %" tbg. S kr rlsed.	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
X_ Subsequent Report Final Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/ 12-30-99 TOOH w/bit. TIH NU WH. RD. Rig Well will operate under D	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att. Idn't rls. SDON. Bee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & pbit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released. CHC #2314.	er Shut of the ser Shut of the ser Shut of the series of t	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON.
X_ Subsequent Report Final Abandonment . Describe Proposed or Comp 12-27-99 MIRU. ND WH. NU latch pkr, wou 12-28-99 RU W/L. TIH w/fr chemical cut t 12-29-99 TIH, tag top of & fish. TIH w/ 12-30-99 TOOH w/bit. TIH NU WH. RD. Rig Well will operate under D	Plugging Back Wat Casing Repair Wat Altering Casing Con X Other - Casing Repair Wat Altering Casing Con X Other - Casing Repair Wat Casing Con X Other - Wat Casing Casing Con X Other - Casing Repair Wat Casing Con X Other Casing Casing Con X Other Casing Casing Con X Other - Wat Casing	er Shut of the service of the servic	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON. 6665'. ND BOP.
	Plugging Back Wat Casing Repair Wat Altering Casing Con X Other - Casing Repair Wat Altering Casing Con X Other - Casing Repair Wat Casing Con X Other - Wat Casing Casing Con X Other - Casing Repair Wat Casing Con X Other Casing Casing Con X Other Casing Casing Con X Other - Wat Casing	er Shut of the service of the servic	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON. 6665'. ND BOP.
	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att. Idn't rls. SDON. Bee point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & pbit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released. CHC #2314.	er Shut of version to the empt to refer	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON. 6665'. ND BOP.
	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - Pleted Operations BOP. TOOH w/ 1 ½" MV tbg. Att Idn't rls. SDON. See point to top of pkr @ 4674 bg @ 4664'. RD W/L. TOOH w/1 fish @ 4633'. Caught fish & p bit, tag up @ 6702'. Est circ w/213 jts 2 3/8" 4.7# J-55 tb released. HC #2314.	er Shut of version to the empt to refer	Fracturing ff o Injection ls Otis perma- ree. TOOH. TIH, DON. TOOH w/tools 722'. SDON. 6665'. ND BOP.