Form 3160-5

*(December 1989)

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED xpires: September 30, 1990

Lease Designation & Serial #:

BLM SF-078615-A

6. If Indian, Allottee/Tribe Nam			31 010		
: LL	ة. بار	I f	Indian,	Allottee/Tribe	Name

SUNDRY NOTICES AND	
Do not use this form for proposals to drill, de	epen or reentry to a different reserve 17-4 17-
SUBMIT IN T	RIPLICATE UIS FAMILIA OF
	Northeast Blanco Unit
	o. Wett Raile and No.:
2. Name of Operator: Blackwood & Nichol	s Co., A Limited Partnership N.E.B.U.# 441
3. Address of Operator: P.O. Box 1237, Dur	ango, CO 81302-1237 9. API Well No.:
4. Location of Well: (Footage, Sec., T., R., M.	
	10. Field & Pool/Expltry Area:
1420' FNL, 1760' FEL - Section 24, T30	I, R8W Basin Fruitland Coal
	11. County or Parish, State:
	Con Juan New Marine
	San Juan, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	IN S PATIE OF ACTION
	_X Abandonment
_X Notice of Intent	Recompletion New Construction
	Plugging Back MAY1 7 1991 Non-Routine Fracturing
Subsequent Report	Casing RepairOIL CON. DIV
	- destrict CON. DIV Later state of
Final Abandonment Notice	— According Colors of the Colores and to Injection
	Other: (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	or Recompletion Report and Log form.
13. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (CL	early state all pertinent details, and give pertinent dates, including estimated Il is directionally drilled, give subsurface locations and measured and true
vertical depths for all markers and zones pe	
4 - 10 - 11 - 12 - 13 - 13 - 13 - 13 - 13 - 13	
 Pick up 14 joints 2-3/8" tubing to tag f Circulate the well with produced water. 	BID.
	'2' (100 feet above the top of the Fruitland Sand) using 75 sx (89 cf) Class B
with 2% CaCl ₂ , and 1/4#/sk cellophane f	ake mixed a 15.6#/gal.
 Pull tubing to 2772' and reverse circula Wait 2 hours, RIH and tag top of cement 	
	9#/gal. mud from cement top to 2358' (50' below top of Kirtland).
	above the top of the Ojo Alamo) using 24 sx (28 cf) Class B mixed a 15.6#/gal.
8. Pull tubing to 2145' and spot 9#/gal. mm	of from 2145; to 1000;. It to surface using 110 sx (130 cf) Class B mixed @ 15.6#/gal.
10. POOH.	to serious daming the sx (130 cl) steads a minet a 13.0% gat.
11. Cut off wellhead.	
12. Install abandonment marker.	SEC ATTACHED FOR
	SEC ATTACHED FOR JOSHDATIONS OF APPROVAL
14. I hereby certify that the foregoing is true	and correct.
Signed: ACKe Co	L RECTOR Title: OPERATIONS ENGINEER Date: 5/10/9/
v.3 /1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	THE OF LINE CHAIRMER DATE:

(This space for Federal or State office use)

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency or the United States any false, fictitious or fraudulent statements or representations as to any matter within its Defision.

AREA MANAGER FARMINATOR NESS JACE 1953

111.000

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LA PLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 441 Northeast Blanco Un

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. Mark Kelly with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 326-6201.

1.15

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made (when applicable):

-- Office Hours: 7:45 a.m. to 4:30 p.m.

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval either on a Sundry Notice (Form 3160-5) or verbally from the Fluids Drilling & Production Section at this office before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs. The Operator is responsible for providing all measuring devices needed to assure proper measurement of materials being used.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations. Unattended pits are to be fenced.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 100 feet in length with 50% excess inside casing or 100% excess when plug is set in open hole or squeezed into perforations. 15.6%/gal slurry weight is to be used when using class B neat cement or when CaCl2 is used. Use the recommended slurry weight of other type cements when they are used (Class C, Pozzolan etc.).
- 5. Any cement plugs placed when well is not full of fluid, or when well may be taking fluid, (i.e. across perfs-unless bridge plug or retainer is used, across bad csg., or fresh water formations) will be tagged (touched) after cement has set to verify proper location.
 - 5a. Testing The first plug below the surface plug shall generally be tested by either tagging the plug with the working pipe string, or pressuring to a minimum pump (surface) pressure of 1000 psig, with no more than a 10 percent drop during a 15-minute period (cased hole only). If the integrity of any other plug is questioned, it must be tested in the same manner. Also, any cement plug which is the only isolating medium for a fresh water interval or a zone containing a valuable mineral deposit should be tested by tagging with the drill string.
- 6. Mud must be placed between plugs. Plugging mud is to be made up with a minimum of 15 lbs/bbl of sodium bentonite, and a nonfermenting polymer.

 Minimum consistency of plugging mud must be 9 lbs/gal and with a minimum viscosity of 50 sec/qt. Fresh water is to be utilized for mixing mud.
- 7. Following the placement of a cement plug, the withdrawl rate for at least the length of the cement plug shall not exceed 30 ft/min, in order to minimize the contamination of the plug.

- 8. Within 30 days after plugging work is completed, file a Sundry Notice (Subsequent Report of Abandonment, Form 3160-5), in quintuplicate with Area Manager, Bureau of Land Management, 1235 La Plata Highway, Farmington, NM 87401. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 9. All permanently abandoned wells are to be marked with a regulation marker (4" pipe extending 4' above the ground line) containing the information as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10. After plugging work is completed the surface is to be rehabilitated in accord with instructions from the Fluids Surface Management Section of the Farmington Resource Area Office.

All above are minimum requirements. The period of liability under the bond of record will not be terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.