В	UNITED STATES ARTMENT OF THE HITERIOR UREAU OF LAND MANAGEMENT		
	NOTICES AND REPORTS ON proposals to drill or to deepen or plux back to pplication for permit—" for such proposal	a different reservoir	0. II III III II II II II II II II II II
I. OIL CAR GO			7. UNIT AGRREMENT NAME
WELL WELL XX OT	HER		8, FARM OR LEASE NAME
Amoco Production Company			Moore C
3. ADDRESS OF OPERATOR			9. WELL NO.
P.O. Box 800, Rm. 1846, Denver, CO 80201 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface			#3 10. FIELD AND FOOL, OR WILDCAT
			Basin Fruitland Coal Gos
		JUN 12 1989	11. BEC., T., R., R., OR SLE. AND BURYEI OR JEGE
1325' FWL, 1120' FSL BUREAU OF LAND MANAGEMEN			Sec. 8-T30N-R8W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, 81.		
	6436' KB		San Juan NM
10. Che	eck Appropriate Box To Indicate Natur	e of Notice, Report, or	r Other Data
•	F INTENTION TO:		SEQUENT REPORT OF:
TEST WATER BHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CABING
RUDOT OR ACIDIZA	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) _Amendmen	
(Other)		Completion or Reco	uits of multiple completion on Well pupiletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPL. proposed work. If well is nent to this work.) *	ETED OFERATIONS (Clearly state all pertinent det i directionally drilled, give subsurface locations	inlis, and give pertinent da and measured and true ver	tes, including estimated date of starting an rtical depths for all markers and zones perti
	d of the following changes		ferenced well.
Also please note	the corrected elevation ab	ove.	
-			
•	Marker	Depth	Elevation
Formation Tops:	Marker	Depth	
•	<u>Marker</u> Fruitland	<u>Depth</u> 2844'	+3592'
•	<u>Marker</u> Fruitland Ignacio Seam	<u>Depth</u> 2844' 3011'	+3592' +3425'
•	<u>Marker</u> Fruitland Ignacio Seam Cottonwood Seam	Depth 2844' 3011' 3090'	+3592' +3425' +3346'
•	<u>Marker</u> Fruitland Ignacio Seam	<u>Depth</u> 2844' 3011'	+3592' +3425'
Formation Tops:	Marker Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	Depth 2844' 3011' 3090' 3135'	+3592' +3425' +3346' +3301' +3240'
Formation Tops: Total Depth:	Marker Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	Depth 2844' 3011' 3090' 3135'	+3592' +3425' +3346' +3301'
Formation Tops:	Marker Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	Depth 2844' 3011' 3090' 3135'	+3592' +3425' +3346' +3301' +3240'
Formation Tops: Total Depth:	Marker Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	Depth 2844' 3011' 3090' 3135'	+3592' +3425' +3346' +3301' +3240' ACCEPTED FOR RECORD AUG 1 5 1989 FARMINGTON RESOURCE AREA
Formation Tops: Total Depth:	Marker Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	Depth 2844' 3011' 3090' 3135'	+3592' +3425' +3346' +3301' +3240' ACCEPTED FOR RECORD AUG 1 5 1989

*See Instructions on Reverse Side

TITLE ___

(This space for Federal or State office use)

Admin. Supv.

DATE .