(November 1983)  (Formerly 9–331)  DEPARTMENT OF THE INTERIOR FORMER OF TREBUNDATION OF THE SURPLY O			Expires August 11, 1985  5. LEASE DESIGNATION AND SURIAL NO.  SF-078580-A  0. IT INDIAN, ALLOTTEE OR TRIBE NAME
SUINDRY INC (Do not use this form for pro Use "APPI	OTICES AND REPORTS ( appearant to drill or to deepen or plug b LICATION FOR PERMIT—" for such p	ON WELLS onck to a different reservoir, roposals.)	The state of the s
OIL GAR WELL OTHER			7. UNIT AGERRMENT NAME
2. NAME OF OPERATOR			8. FARM OR LEASE HAME
Amoco Production Co	ompany		Moore B
	1846 Danwar CO 9030	. DEPENDED	P. WALL NO.
P.O. Box 800, Rm. 1846, Denver, CO 80201			#3 10. FIELD AND FOOL, OR WILDCAT
At surface			•
1290' FNL, 1220' F	EL	JUN 121989	Basin Fruitland Coal Gas
	Bu	TREAU OF LAND MANAGEMENT	Sec. 5-T30N-R8W
14. PERMIT NO. 15. ELEVATIONS (Show whether DF.		, RT. GR. etc.)	12. COUNTY OR PARISH 13. STATE
	6283' KB		San Juan NM
16. Check	Appropriate Box To Indicate N	Julius of Notice Report of	
HOTICE OF IN			
TEST WATER SHUT-OFF	PULL OR ALTER CASING		EQUANT REPORT OF:
FRACTURE TREAT	MULTIPLE COMPLETE	WATER SHUT-OFF	MEPAIRING WELL
SHOOT OR ACIDIZA	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING
REPAIR WELL	CHANGE PLANS	(Other) Amendmen	ABANDONMENT*
(Other)		(Norz : Report resu	its of multiple completion on Well
Please be advised o	of the following change to corrected elevation	es for the above ref	enpletion Report and Log form.)  ies, including estimated date of starting any tical depths for all markers and zones perti-  erenced well.
	te corrected elevation	above.	
Pormeties Test	36 1		
Formation Tops:	Marker	Depth	Elevation
Formation Tops:	Fruitland	2757 <b>'</b>	<u>Elevation</u> +3516'
Formation Tops:	Fruitland Ignacio Seam	2757 <b>'</b> 2923 <b>'</b>	+3516' +3360'
Formation Tops:	Fruitland Ignacío Seam Cottonwood Seam	2757' 2923' 2998'	+3516' +3360' +3275'
Formation Tops:	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam	2757' 2923' 2998' 3055'	+3516' +3360' +3275' +3218'
	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998'	+3516' +3360' +3275'
Formation Tops:  Total Depth: 3359	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180'
	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218'
Total Depth: 3359	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180'
Total Depth: 3359	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180' ACCEPTED FOR RECORD  AUG 1 5 1989  FARMINGTON RESOURCE AREA
Total Depth: 3359	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180' ACCEPTED FOR RECORD  AUG 1 5 1989  FARMINGTON RESOURCE AREA
Total Depth: 3359	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs  sing Point: 2893'	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180' ACCEPTED FOR RECORD  AUG 1 5 1989  FARMINGTON RESOURCE AREA
Total Depth: 3359 7" Intermediate Cas	Fruitland Ignacio Seam Cottonwood Seam Cahn Seam Pictured Cliffs  sing Point: 2893'	2757' 2923' 2998' 3055' 3103'	+3516' +3360' +3275' +3218' +3180' ACCEPTED FOR RECORD  AUG 1 5 1989  FARMINGTON RESOURCE AREA

\*See Instructions on Reverse Side

DATE \_

TITLE \_