In Lieu Form 3 (June 1	DEPARTMENT C	STATES OF THE ENTERIOR OF MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
		D REPORTS ON WELLS recentry to a different reservoir. Use "APPLICATION	FOR SZI
Lady			5. Lease Designation and Serial No. SF-078771
		203213767	6. If Indian, Allottee or Tribe Name
	SUBMIT IN	TRIPLICATE AUG 2001	7. If Unit or CA, Agreement Designation Rosa Unit
1.	Type of Well ☐ Oil Well	Other OILOON DIV N	8. Well Name and No. Rosa Unit No. 8B
2.	Name of Operator Williams Production Company LLC	EUM 68 P	9. API Well No.
3.	Address and Telephone No. C/O Walsh Engi 7415 East Main, Farmington, NM 87402	10. Field and Pool, or Exploratory Area Blanco Mesaverde/Basin Dakota	
4.	Location of Well (Footage, Sec., T., R., M., or 2010' FNL & 2170' FWL Sec 26, T31N, Ro	11. County or Parish, State Rio Arriba, NM	
	CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
	TYPE OF SUBMISSION	Т	YPE OF ACTION
	☑ Notice of Intent	☐ Abandonment ☐ Recompletion	⊠ Change of Plans ☐ New Construction ☐ Non-Routine Fracturing
	☐ Subsequent Report	☐ Plugging Back	Thou-roung tractming

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

☐ Casing Repair

☐ Altering Casing

☐ Other See Below

■ Water Shut-Off

☐ Dispose Water

Log form.)

☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and

Williams Production Company LLC proposes to drill and complete the Rosa Unit 8B as a Mesaverde/Dakota dual well as per the attached drilling and completion procedure. The well is currently permitted as a stand alone Mesaverde well. No changes on the surface will occur from this proposed change of plans.

Attached: New plat showing Mesaverde/Dakota and new drilling & completion procedure.

☐ Final Abandonment

14.	I hereby certify that the foregoing is true and corre	ct	, i de cipling e exploration, per e el co		
	Signed .	(John C. Thompson) Title	Agent/Engineer	Date	07/26/01
	(This space for Federal or State office use)				
	Approved by	Title		Date	8/21/01

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side



District I State of New Mexico PO Box 1980. Hobbs, NH 88241-1980 Form C-102 Energy, Hinerals & Natural Resources Department Revised February 21, 1994 Instructions on back Submit to Appropriate District Office PO Drawer DO. Artesia, NM 88211-0719 OIL CONSERVATION DIVISION State Lease - 4 Copies District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM 87504-2088 District IV PO Box 2088, Santa Fe, NM 87504-2088 AMENDED REPORT WELL LOCATION AND ACREAGE DEDICATION PLAT API Number Pool Code Pool Name 72319 / 71599 Blanco Mesaverde / Basin Dakota Property Code Property Name Hell Number 17033 ROSA UNIT 8B OGRID No. *Operator Name Elevation 120782 WILLIAMS PRODUCTION COMPANY 6311' ¹⁰ Surface Location UL or lot ro. Sect ton Let Joh Feet from the North/South line Feet from the East/Nest Jane F RIO 26 31N **6W** 2010 NORTH 2170 WEST ARRIBA ¹¹Bottom Hole Location If Different From Surface UL or lot no. Feet from the North/South line East/Nest line County st Dedicated Acres ¹⁵ Joint or Infill M Consolidation Code 320 - W/2NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION OPERATOR CERTIFICATION 5278.681 I hereby certify that the information contained herein is true and complete to the best of av impulator and belief 2010 OIL CON. D CIST. Steve Nelson Printed Name Agent, Nelson Consulting 2170 5280.00 April 2, 2001 Date 18 SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by se or under my supervision, and that the same is true and correct to the best of my belief. SEPTEMBER 9. 2000 685



WILLIAMS PRODUCTION COMPANY

OPERATIONS PLAN

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:

7/26/2001

WELL NAME:

ELEVATION:

Rosa #8B

FIELD:

Blanco MV/DK

SURFACE LOCATION:

SF/4 NW/4 Sec. 26- T31N-R6W

SURFACE:

BLM

6311" GR

Rio Arriba, NM

MINERALS:

BLM

LEASE#

SF-078771

MEASURED DEPTH:

8038

I. GEOLOGY:

Surface formation - San Jose

A.: FORMATION TOPS: (KB)

<u>D</u>
23'
73'
13'
68'
88'
38'
7 1 6 8

- B. <u>LOGGING PROGRAM</u>: IND/GR/TEMP from TD to the Intermediate Casing Shoe. DEN/Neutron/GR (selected intervals by on-site Geologist). Subject to change as wellbore conditions dictate.
- C. <u>NATURAL GAUGES</u>: Gauge any noticeable increases in gas flow. Guage well @ 5800' and before TOH for logs @ 7954'. Record all gauges in Tour book and on morning reports.

II. DRILLING

- A. <u>MUD PROGRAM:</u> Clear water with benex to 7" casing point. LSND to log and run pipe. Treat for lost circulation as necessary. Obtain 100% returns prior to cementing. Notify Engineering of any mud losses.
- B. <u>BOP TESTING:</u> While drill pipe is in use, the pipe rams will be function tested not less than once each day. The blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the rams will be tested to 1500 psi. The drum brakes will be inspected and tested each tour. All tests, inspections and SPR's will be recorded in the tour book as to time and results.

IIL MATERIALS

A. CASING PROGRAM:

CASING TYPE	HOLE SIZE	<u>DEPTH</u> +/- 250'	CASING SIZE	WT. & GRADE 32.75# H-40
Surface Intermediate	9-7/8"	+/- 3613'	7-5/8"	26.4# K-55
Prod. Casing	6-3/4"	+/-8053'	5-1/2"	17.0# N-80

B. FLOAT EQUIPMENT:

- SURFACE CASING: 10-3/4" notched regular pattern guide shoe. Run (1) Standard centralizer on each of the bottom (3) Joints.
- 2. INTERMEDIATE CASING: 7-5/8" cement nose guide shoe with a self-fill insert float. Place float one (1) joint above the shoe and five (5) centralizers, spaced every other joint, starting with the float collar. Place turbulent centralizers, at 120' intervals, starting at 1500' to the surface. Total centralizers (5 regular and 13 turbulent).
- 3. PRODUCTION CASING: 5-1/2" whirler type cement nose guide shoe with a latch collar on top of 20' bottom joint. Place 20' marker joint on top of 10 th joint and one above 5100'.

C. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- SURFACE: Use 165sx (225cu.ft.) of class "Type III" with 2% CaCl2 and 1/4# of cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5 #/gal.). 125% excess to circulate the surface. WOC 12 hours. Test to 1500#.
- 2. INTERMEDIATE: Lead: 580sx (1208cu.ft.) of class "Premium Lite" 65/35, Type III/Poz with 8% gel and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail: 250sx (376cu.ft.) of class "Type III" with 1/4# cello-flake/sk (Yield = 1.39 cu.ft./sk, Weight = 14.5#/gal.). 100% excess in lead and tail to circulate to surface. Total volume = 1552 cu.ft. WOC 12 hours. Run a
 - 3. PRODUCTION STRING Lead: 305 sx (419 cu.ft.) of class 50/50, Poz/Class H with 4% gel, 2% kcl, 0.2% CD-32, 4.0% Phenoseal, 0.6% FL-50 and 1/4#/sk cello-flake. (Yield = 1.38 cu.ft./sk, Weight = 13.4 #/gal.). Tail: 100 sx (150 cu.ft.) of class "H" with 35% silica flour, 1.5% FL-62, 0.3% CD-32, 0.2% A-2, and 1/4# cello-flake/sk, (Yield = 1.50 cu.ft./sk, Weight = 15.9 #/gal.) Batch mix tail slurry. Displace cement at a minimum of 8 BPM. Use 50% excess in lead and tail to bring cement top 150' into intermediate casing. Total volume 569 cuft. WOC 12 hours. cuft. WOC 12 hours.

IV COMPLETION

A. CBL

1. Run Cement Bond Log across all intervals to be perforated and find Top of Cement behind all casing strings if cement not circulated to surface..

B. PRESSURE TEST

1. Pressure test 7 5/8" & 5-1/2" casing to 3300# for 15 minutes.

C. STIMULATION

- 1. Stimulate Dakota with approximately 70,000# of 20/40 sand in x-link foam.
- 2. Isolate Dakota with a RBP.
- 3. Stimulate Point Lookout with approximately 80,000# of 20/40 sand in slick water.
- 4. Isolate Point Lookout with a RBP.
- 5. Perforate the Menefee/Cliff House as determined from the open hole logs.
- 6. Stimulate with approximately 80,000# of 20/40 sand in slick water.
- 7. Test each zone before removing bridge plugs.

D. RUNNING TUBING

- 1. <u>Dakota</u>: Run 2-1/16", 3.25#, J-55, EUE tubing with 1/2 mule shoe on bottom, SN with pump-out plug on top of bottom joint. Use production packer (w/ 5 Seal Units) to isolate Dakota from Mesaverde. Land tubing approximately 100' below top Dakota perf.
- 2. <u>Mesa Verde:</u> Run 2-1/16", 3.25, J-55, EUE tubing with a SN on top of bottom joint. Land tubing approximately 25' above the bottom Point Lookout perforations.

John Thompson

Engineer

Walsh Engineering & Production

Well Control Equipment Schematic for 2M Service

Attachment to Drilling Technical Program

Typical Mesaverde/Dakota BOP setup

