Form 9-881 s. (Feb. 1951)							
		•					

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

and Office	Santa Fe
	080776-A
1_1_	

	SUBSEQUENT	REPORT OF SHOOTING OR A	CIDIZING			
NOTICE OF INTENTION TO TEST WATER SHUT-OFF			SUBSEQUENT REPORT OF ALTERING CASING			
REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR					
NOTICE OF INTENTION TO SHOOT OR ACIDIZE			SUBSEQUENT REPORT OF ABANDONMENT.			
			SUPPLEMENTARY WELL HISTORY			
	waver a					
OVE BY CHECK MARK	NATURE OF REPOR	F, NOTICE, OR OTHER DATA)				
	. No	vember 8	, 19. <u>62</u>			
	(A.1)					
1550 ft. from	line and	$\frac{990}{\mathbf{W}}$ ft. from \mathbf{E}	line of sec. 25			
30-N	JO-M	N.M.P.M.	्र _{ास} ्त व्यवस्था			
	(Range)	(Meridian)				
Sen Juan	- Subdivision)	Nev M	exico !!			
			1982			
or above sea lev	el is 6320	ft.	1. 7. –			
DETAI	IS OF WOR	v	YEVRUS TABLES OF S			
			GOTON, CLW MEXICA			
ctive sands; show size ing points, and all ot	s, weights, and len ther important pro	gths of proposed casings; ind posed work)	licate mudding jobs, coment-			
w/51,494 gall I.R. 55.2 BPM 2 SPF); 4578- ater, 48,000/	lons water, M. Max pr -84;4530-42 # sand. Fl	50,000# sand. 3300#, tr pr 230 ! (1 SPF); msh w/3360 gallo	Flush 00-2400#. 4 drops of ons water			
t receive approval in v	writing by the Geol	ogical Survey before operation	PRINTED TO COMPANY DE			
Ges Company			The state of the s			
			- 			
Mexico	E	y COLOURAL SIGNED	H.E. McANALLY			
	CASING CASING COVE BY CHECK MARK 30-N (Twp.) Ben Juan (County of the county of t	SUBSEQUENT SUPPLEMENT WATER OVE BY CHECK MARK NATURE OF REPORT NOTE BY CHECK MARK NATURE OF REPORT NATURE OF REPORT	SUBSEQUENT REPORT OF ABANDONMENT. REPORT OF ABANDONMENT. SUBSEQUENT FORCE. SUBSEQUENT REPORT OF ABANDONMENT. SUBSEQUENT REPORT OF ABANDONMENT. SUBSEQUENT REPORT OF ABANDONMENT. SUBSEQUENT REPORT. NOVEL BY SUBSEQUENT REPORT. SUBSEQUENT REPORT. NOVEL BY SUBSEQUENT REPORT. SUBSEQUENT SUBSEQUENT. SUBSEQUENT. SUBSEQUENT SUBSEQUENT. SUBSEQUENT. SUBSEQUENT SUBSEQUENT			