UNITED STATES

DEPARTMENT OF THE INTERIOR

bunary not	ices and Reports on Wells		
. Type of Well GAS	FEB 2001	6. I	ease Number F-078510 f Indian, All. or ribe Name
Name of Operator BURLINGTON RESOURCES OIL	O RECEIVE O OLOON, DE OBT. 8		nit Agreement Name
. Address & Phone No. of Opera PO Box 4289, Farmington, NM	tor		Well Name & Number Exnard #2 PI Well No.
. Location of Well, Footage, S		3	0-045-10922 Tield and Pool
1765'FNL, 1140'FEL, Sec.7, T	-31-N, R-8-W, NMPM	11.	lanco Mesaverde County and State San Juan Co, NM
CHECK APPROPRIATE BOX TO IN		ORT, OTHER D	ATA
Type of Submission Notice of Intent	Type of Action Abandonment Cha	ange of Plan	S
	Recompletion Nev	v Constructi	on
X Subsequent Report		n-Routine Fr cer Shut off	
Final Abandonment	Altering Casing Cor X Other - Tubing repair		
	,		
3. Describe Proposed or Comp			
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7		3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. 7 2 3/8" 4.7# J-	pleted Operations TIH, tag up @ 5868'. TOOH w/2	3/8" tbg. T 99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. To a sign released.	pleted Operations FIH, tag up @ 5868'. TOOH w/2 -55 tbg, set @ 5800'. SN @ 579	99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. To a 3/8" 4.7# J-Rig released.	pleted Operations TIH, tag up @ 5868'. TOOH w/2	99'. ND BOP.	IH w/184 jts NU WH. RD.
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. To a sign of the state of the	pleted Operations FIH, tag up @ 5868'. TOOH w/2 -55 tbg, set @ 5800'. SN @ 579	et.	NU WH. RD. ≥ 2/7/01 TIW
2-2-01 MIRU. SDON. 2-5-01 ND WH. NU BOP. To 2 3/8" 4.7# J-Rig released.	e foregoing is true and corre	et.	NU WH. RD.

Sw. Series