

60-5
90)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

97 APR 29 PM

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

070 FARMINGTON, NM

Use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
14-20-0603-639

6. Indian, Allottee or Tribe Name
NMI

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

of Well.
Oil Well Gas Well Other

8. Well Name and No.
KING KONG

Name of Operator
ACTION OIL COMPANY, INC.

9. API Well No.
15

Address and Telephone No.
301 EAST MAIN, FARMINGTON, NM 87402 327-0311

10. Field and Pool, or Exploratory Area
Just Creek Dakota

Location of Well (Footage, Sec., T., R., M., or Survey Description)
1810' FNL & 1980' FEL SEC 4, T. 30 N., R. 17 W.

11. County or Parish, State
SAN JUAN COUNTY

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Well #15 King Kong has been down because of downhole problems. The well does'nt have a casing leak, it is a rubber packing at the top of the tubing that leaked when this well was not producing. We have put a new pump; replaced some tubing, and a new packing on top of the tubing to repair this well. This was done on April 18, 1997.

I hereby certify that the foregoing is true and correct

Signature of [Name] Title [Title]

ACCEPTED BY [Signature] REGULAR

Approved by [Signature] Title [Title]

Date MAY 01 1997

FARMINGTON DISTRICT OFFICE