Union Texas Petroleum Corporation State Com. 31-8 No. 1 905 ft./S; 790 ft./W line Sec. 2, T31N, R8W San Juan County, New Mexico

Item No. 31 and No. 32
Perforation and Fracture Record

## Lower Mesaverde

Perforations: 5760, 61, 62, 63, 64, 5831, 32, 33, 34, 35, 36, 39, 40, 41, 42, 43, 58, 59, 60, 87, 88, 89, 93, 94, 95, 96, 97, 98. (Total of 28 - 0.38" holes)

Acidized with 48 bbl. of 15% HCl and ball sealers. Frac'd. with 1258 bbl. of slick water containing 2% KCl and 47,500 lb. of 20-40 sand.

## Upper Mesaverde

Perforations: 5576, 77, 78, 79, 80, 81, 82, 97, 98, 99, 5600, 01, 02, 03, 04, 09, 10, 11, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 64, 65, 66, 67, 68, 69, 70. (Total of 46 - 0.38" holes)

Acidized with 3200 gallons of 15% HCl and 70 ball sealers. Frac'd. with 1709 bbl. of slick water containing 2% KCl and 93,100 lb. of 20-40 sand.

