Submit 3 Copies
to Appropriate
District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office	A special vol. 2 special control of	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATI P.O.Box 2		WELL API NO.
DISTRICT II Santa Fe New Mexic		30 045 25560
P.O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS OF	N WELLS	-
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DI DIFFERENT RESERVOIR. USE "APPLICATION F (FORM C-101) FOR SUCH PROPOSALS	EEPEN OR PLUG BACK TO A OR PERMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well:		Stedje Gas Com
OIL GAS WELL OTHER		Joseph San San
2. Name of Operator		8. Well No.
Amoco Production Company Attn: Ed N	icholson	lE .
3. Address of Operator		9. Pool name or Wildcat
P.O. Box 800, Denver, Colorado 80201		Basin Dakota
4. Well Location		
Unit Letter A : 1190 Feet From The North	Line and 830	Feet From The _East Line
Section 27 Township 30N	Range 12W N	IMPM San Juan County
10. Elevation (Show w 5483'	heiher DF, RKB, RT, GR, eic.) KB	
11. Check Appropriate Box to Indica	ate Nature of Notice. Re	port, or Other Data
NOTICE OF INTENTION TO:	· · ·	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	7	
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEN	NENT JOB
OTHER: <u>Bradenhead Repair</u> X	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent det work) SEE RULE 1103.	alls, and give pertinent dates, includ	ling estimated date of starting any proposed
Amoco intends to perform the attached work	10 15 17 1 17 P	13-3-1-1-1-1-1-1
	cover brocedure in the	liminate bradenhead
pressure.	OCT 2 3 1992	
	L CON. DIV.	
	L CON. DIV	
	DIST. 3	
U ,	_	
. ~ .		
NOTE: FAXED ON 10-26-92 TO STATE OF VERBAL APPROVAL BY FRANK CHR	E NEW MEXICO	(505) - 234-1,170
FAXED ON 10-26-92 10 STATE	WE - RECUEST	LOCATION AT LETAK
VERBAL APPROVAL BY FRANK CATH	NEZ - NEUWEST	ZUCHINON OF CLIM,
\ ON 10-26-92 AM.		
I hereby certify that the information above is true and complete to the best of m	y knowledge and belief.	
5 W Machal		in la la
SIGNATURE CIC PROPERTY	mre Staff Admin.	Analyst DATE 10/26/9
TYPE OR PRINT NAME Ed Nicholson		TELEPHONE NO.
(This space for State Use)		DIST III
Original Cigned by CHANLES GHOLSON	TILDEPUTY OIL & GAS IN	SPECTOR, DIST. #3 DATAGE 28 1992

STEDJE GAS COM WELL #1E DAKOTA COMPLETION SEC 27A-30N-12W WORKOVER PROCEDURES

- 1) Contact NMOCD before starting repair work.
- 2) Install anchors, if necessary or test.
- 3) MI x RUSU. Note tbg, csg x bradenhead pressures.
- 4) Rig up blow down lines x blow down csg.
- 5) Kill tbg w/2% KCL water, if necessary.
- 6) NDWH. NUBOP's.
- 7) Pick up tbg x tag PBTD. Tally OOH w/tbg. Visually inspect x replace bad joints, if necessary.
- 8) TIH w/bit x scraper to 6100'. POOH. TIH w/RBP x PKR x set RBP @ 6075'. TOOH one joint x set PKR x pressure test RBP to 1500#.
- 9) If csg fails to pressure test, isolate casing leak interval x establish injection rate x pressure into leak w/water. Contact Sandi Braun (X5245) w/results.
- 10) Additional procedures will follow based on results.

Amoco Production Company

SUBJECT _____

ENGINEERING CHART

Life —	
Annn	

Of

Sheet No.

Appn
 Date

	_			7						,	-								,	······································				Ву				
								<u>L</u>																				
						ļ	,	DT	EI	176	<u> </u>	6	5	C	とっている	<u>1</u>	#/	LE	Ī									
						<u> </u>				DAY	<u>a</u>	A	_(q	hp	عي	<u>D</u> 'c	>~	}									
_ -								(on	hPc	EI	ای	را	DA	TE'	-	7/	8	<u> </u>									
_ .			<u> </u>			<u> </u>			De	<u> </u>	27	A	- :	30	7	- 12	پر	دا	<u>.</u>									
									SF	m	2	tu	47		ررو	باج	1	hE	XI	م								
			ļ			ļ		<u> </u>																				
_ _				<u> </u>		<u> </u>]																				
30		37 60:	<u>ട'</u>]		 		<u> </u>																
4	\	60	<u> </u>																									-
44		32	20																									
\h		34	72															(ල: උ:	18	,	DL	1#	I	22	 		
(4) (1)		40	75	}															6	SA	3	34	7					
d		4	119	3'							-									~	7	D S	\ \ \(\tau \)	Ę.	400			_
ر ا		5	72 75 119 341	}		-				\															<u> </u>	[
X H		61	000	BI	(E)																						-	-
K		61	54	-								1				-												-
Ť			Ī				1-	 												 					<u> </u>	-	_	-
				<u> </u>	 		-	ļ									\mathcal{L}	/ ¬	200		0	41	la	-1				-
									-																_	-		
							1-										21			<u> </u>		1710	د يا	155	20	Crc	CE	
+			ļ		<u> </u>	-							<u> </u>										 					-
_							1											 					 	 -		_		
\dashv					 -		 		-														<u> </u>					-
┥,	DΑ	Y.	2:	150	F:	-				<u> </u>		 		V			73	8"		<u> </u>	<u> </u>			,	ļ			
\dashv			_		<u>5</u> 5.	6	J		 -	 -			_	الا ا				18	_	TC	<u>} </u>	<u>62</u> .	58					
- -				ì	30					F -																		
-			ļ ——		76 -		3/2-		=	<u> </u>	<u> </u>	ļ						<u> </u>										
-			 		<u> </u>				<u> </u> ,																			
- -					 		 -		(ļ						
- -						<u> </u>		ļ				ļ				1	īVI	-1/-										
										<u> </u>					,		11,		/c	.5	 	72	5	2	A	6	33	8
-					ļ				<u> </u>	67	0		3.	35 30													•	
- -											10	 	63	20														
- -						ļ																						
_						<u> </u>	-		 																			
_1 -									<u> </u>	<u> </u>														 				
QK	7/6	MA	DY	\ \\	L	æ	172	1	EVS	ai	502A	ME	20	\bigcup	CH CH	t												



