F

30-045-28602

10-03-91

F. Loc	944/N; 723/W Cu.ft. Sx. Int		Elev	5889 GL	389 GL Spd.		Comp		TDCu. ft.		3	
asing Ssg,Perf.	@w [`]	Sx. Int		w	Sx. Pr. Prod. Stim.	@	\	v	Sx. T		_@	† Gas
					Grav		1st De	I. <u>Gas</u>				N S
P	BO/D MCF/D After	Hrs. SICP	ps	SI After	Days GOR		1st De	ı. <u>Oil</u>				
TOPS		NITD X		Well Log		TEST DATA						
Ojo Alamo		C-103		Plat	X	Schd.	PC	Q	PW	PD	D	Ref.No
Kirtland		C-104		Electric Log				ļ	<u> </u>	<u> </u>	 	
Fruitland				C-122					ļ		 	
Pictured Cliffs		Ditr		Dfa						<u> </u>	ļ	
Chacra		Datr		Dac				ļ	ļ	<u> </u>	—	
Clif louse								-	 -	ļ	ļ	
Menefee								ļ	_	↓	 -	
Point Lookout						ļ	<u> </u>		<u> </u>	 		
Mancos						ļ	<u> </u>	ļ	 -	ļ	+-	
Gallup						ļ		ļ	 		 	
Greenhorn						ļ		ļ		 	<u> </u>	-
Dakota							ļ	ļ — —	+	-	+	+
Entrada							 	-	 	+	+	+
		K0810	EJA		Acres 40,61		<u> </u>	1		<u>.L</u>	<u> </u>	

Sangre De Cristo #6 D-34-30N-11W

ORVILLE SLAUGHTER

Oswell Farm Co. SJ \$ 34 1 30N R 11W UD Oper. Orville Slaughter Late. Sangre De Cristo No. 6

NMSF-043260-A (WC) 3162.3-1.0 (07337)

.,,,

JUL 0 7 1994

Mr. Oraville Slaughter 2626 Adams Street Denver, Colorado 80205

Dear Mr. Slaughter:

You are required to request surface rehabilitation instructions from this office if any construction activities have occurred on the referenced drill site. If this office does not receive comment within 30 days, it will be presumed that no construction occurred. Later discovery that construction activities have occurred, may result in assessment of liquidated damages.

Sincerely,

e/e Ken Townsend

Ken Townsend
Chief, Branch of Drilling
 and Production

Enclosure

cc: New Mexico Oil Conservation Division 1000 Rio Brazos Rd., Aztec, NM 87410

> DECEIVED Jul 1 1 1994

ABANDONED LOCATION DIEN.