UNITED STATES DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT



	Reports on Wells	7 PM 31 23	
l. Type of Well GAS	070 FA		
		7.	Unit Agreement Name
2. Name of Operator BURLINGTON RESOURCES OIL & GAS CO	OMDANTA		
	OMPANI	8.	Well Name & Number
PO Box 4289, Farmington, NM 87499	(505) 326-9700	9.	Turner Federal #2 API Well No.
Location of Well, Footage, Sec., T, 1650'FNL, 1650'FEL, Sec.13, T-30-N,	R, M	10.	30-045-60206 Field and Poci.
G G	R-10-W, NMPM	11.	Blanco Mesavende County and State San Juan Co, NM
Subsequent Report Pl Ca Final Abandonment Al	Lugging Back asing Repair	Conversion to	iion Fracturing Ef
3. Describe Proposed or Completed Or	perations		
3. Describe Proposed or Completed Or It is intended to repair the tubi procedure and wellbore di	ing in the subject	well accordi	ng to the attached
It is intended to repair the tubi	ing in the subject	well according	N. Oran
It is intended to repair the tubi	ing in the subject	well according	N. Oran
It is intended to repair the tubing procedure and wellbore di	ing in the subject		N. Oran
It is intended to repair the tubic procedure and wellbore di	ing in the subject	o)	ECE STA
It is intended to repair the tubic procedure and wellbore dispersion of the second signed of the second signed of the second sec	ing in the subject agram. ing is true and co	o)	ECE STA

WORKOVER PROCEDURE -- TUBING REPAIR

TURNER FEDERAL #2
Blanco Mesaverde
Sec. 13, T3CN, R10W
San Juan Co. New Mexico
DPNO: 47941A

- 1. Comply to all NMOCD. BLM, and BROG regulations. Conduct daily safety meetings for all personnel on location. Notify BROG Regulatory (Peggy Bradfield, 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document the approval in Dims/Wims. As much time as possible to the pump time is needed to the Agency to be able to show up for the cement job.
- 2. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and BROG safety regulations.
- 3. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 4. TIH and tag bottom. Record depth. TOH with 2 3/8" tubing (183 jts.). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations). LD perforated joint.
- 5. PU and RIH with 3 7/8" bit and 4 1/2" casing scraper to PBTD, 5549'. TOH and LD bit and scraper.
- 6. RIH open ended with tubing, SN one joint off bottom, (rabbit tubing in derrick before running in hole). CO with air. Land tubing @ bottom perforation, 5538'.

7. ND BOP, NU wellhead, rig down, move off location and restore location.

Recommended

Approval:

Drilling Superintendent

CONTACTS:

Operations Engineer

Gave White

326-9875

Turner Federal #2

CURRENT -- 12-12-96

Blanco Mesaverde DPNO 47941A

1650' FNL. 1650' FEL.

Section 13, T-30-N, R-10-W, San Juan County, NM Longitude / Latitude: 36° 48.8745' — 107° 49.9365'

Spud: 12-5-50 Completed: 3-6-51 Elevation: 6519' (GL) 6529' (KB)

Logs: Bond-Gamma, Casing Inspection, Caliper, Correlation, TS

Compression. B6 Workover(s):

7/64: Pull tubing, tubing parted. Cut tubing and left perforated and anchor joints in hole. Ran 4 1/2" casing, cmt. perf, and frac. Land 2 3/8" tubing @ 5483'.

4/96: Plunger Installation


Fruitland @ 2803

Pictured Cliffs @ 3178'

Cliff House @ 4786

Menefee @ 5002'

Point Lookout @ 5408



CASING PRESSURES		PRODUCTION HISTORY		INTEREST		PIPELINE
Initial SICP (3/51): 1.026 p	1.026 psi	Gas Cum: Current (10/96)	7.5 Bcf 338 Mcf/d	GiWI: 1	100.00%	EPNG
Current SICP (4/93): 352 psi	Oil Cum:	18.4 Mbo	NRI:	75. 56%		
		Current (10/96)	9 Bo/cl	SJBT:	0.00%	