Submit 3 Copies State of New Mexico Energy, Minerals and Natural Resources Department to Appropriate Form C-103 District Office Revised 1-1-89 DISTRICT I OIL CONSERVATION DIVISION P.O. Box 1980, Hobbs, NM 88240 WELL API NO. P.O. Box 2088 Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 5. Indicate Type of Lease DISTRICT III FEE X STATE 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: WELL XX WELL NIELSEN OTHER 2. Name of Operator 8. Well No. #1 Snyder Oil Corporation 3. Address of Operator 9. Pool pame of Wildert OTA P.O. Box 2038 Farmington, NM 87499 4. Well Location 1850 Feet From The SOUTH Unit Letter _ EAST Line and Feet From The Line 13W 31N San Juan Township Range NMPM County 10. Elevation (Show whether DF, RKB, RT, GR, etc. 5825' GL - 5837' KB Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** ХX COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: OTHER:_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed ROBERT L. BATLESS Bayless Drilling Company intends to condition this well for water disposal in the Mesa Verde. Snyder Oil Corp. has agreed to plug back the Dakota and Gallup formations prior to turning over operation of this well to Bayless. OUL COM. DIV.

DIST. 3

I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE <u>District</u> Engineer 5/06/94 Wayne L. Converse 632-8056 TYPE OR PRINT NAME TELEPHONE NO (This space for State Use)

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 43 Original Signed by CHARLES GHOLSON DATE MAY - 6 1994

			-	
e ^{gg}				
		4		
•				

Nielsen #1-17 (Dk)
Unit I, Sec. 17, T31N, R13W
San Juan County, New Mexico

PLUG AND ABANDONMENT PROCEDURE:

- 1. MOL and RUSU. Comply to all NMOCD, BLM and Snyder safety rules and regulations. Blow well down; kill with water if necessary. ND wellhead and NU BOP and stripping head; test.
- POH and LD 1-1/2" tubing. PU 5-1/2" casing scraper and round trip to 6548'. PU 5-1/2" cement retainer and 2" tubing work string; RIH and set at 6548' (above Dakota perfs); pressure test tubing to 1000#; pump into perfs.
- 3. Plug #1 under CR at 6548' to 6669' with 32 sxs Class B cement (100% excess), squeeze 27 sxs below CR then spot 5 sxs on top. POH to 4992' and circulate hole; pressure test casing to 500#.
- 4. Plug #2 from 4992' to 4892' with 17 sxs Class B cement (Gallup top at 4992'). POH and LD setting tool.




