State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	API # (assigned by OCD) 30-045-10783
Type of Well	5. Lease Number
GAS	6. State Oil&Gas Lease
Name of Operator	E-286-14 7. Lease Name/Unit Nam
BURLINGTON	
RESOURCES OIL & GAS COMPANY	Brookhaven Com A 8. Well No .
Address & Phone No. of Operator	2
PO Box 4289, Farmington, NM 87499 (505) 326-9700	 Pool Name or Wildca Blanco Mesaverde
Location of Well, Footage, Sec., T, R, M 990'FNL, 1650'FEL, Sec. 16, T-31-N, R-10-W, NMPM, San Jua	10. Elevation: n County
Type of Submission Type of Action	
X Notice of Intent Abandonment Ch	ange of Plans w Construction
Subsequent Report Plugging Back No	w Construction n-Routine Fracturing
Casing Repair Wa	ter Shut off
Final Abandonment Altering Casing Co X Other - Tubing repair	nversion to Injection
B. Describe Proposed or Completed Operations	ll according to the attached
It is intended to repair the tubing in the subject we procedure and wellbore diagram.	ll according to the attached DEGENERATE DEGENERATE

WORKOVER PROCEDURE -- TUBING REPAIR

BROOKHAVEN COM A #2
Blanco Mesaverde
Sec. 16. T31N, R10W
San Juan Co., New Mexico
DPNO: 6590

- 1. Comply to all NMOCD, BLM, and BROG regulations. Conduct daily safety meetings for all personnel on location. Notify BROG Regulatory (Peggy Bradfield, 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document the approval in Dims/Wims. As much time as possible to the pump time is needed to the Agency to be able to show up for the cement job.
- 2. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and BROG safety regulations.
- 3. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 4. TIH and tag bottom. Record depth. TOH with 2 3/8" tubing (174 jts.). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations).
- 5. PU and RIH with 3 7/8" bit and 4 1/2" casing scraper to PBTD, 5538'. TOH and LD bit and scraper.
- 6. RIH open ended with tubing, SN one joint off bottom, (rabbit tubing in derrick before running in hole). CO with air. Land tubing @ bottom perforation, 5496'.
- 7. ND BOP, NU wellhead, rig down, move off location and restore location.

Recommended:

Approval:

Drilling Superintendent

Operations Engineer

CONTACTS: Operations Engineer

Gaye White

326-9875

Brookhaven Com A #2

CURRENT -- 12/09/96

Blanco Mesaverde **DPNO 6590**

990' FNL, 1650' FEL, Section 16, T-31-N, R-10-W, San Juan County, NM

Longitude / Latitude: 36°54.16626' - 107°53.03376'

Spud: 2-4-53 Completed: 3-16-53 Elevation: 6165' (GL)

6175' (KB) Logs: IEL, GRI, TS Workover(s):

6/72: Cut off stuck tubing, cement open hole & perfed & squeezed Oio Alamo @ 1437'. Sidetracked with 4 1/2" casing. Perfed, fraced & landed 2 3/8" tubing.

Ojo Alamo @ 1918' Kirtland @ 2008'


Fruitland @ 2530'

Pictured Cliffs @ 2952' Lewis @ 3020'

Cliff House @ 4646'

Menefee @ 4818'

Point Lookout @ 5218'



CASING PRESSURES		PRODUCTION HISTORY		INTEREST		PIPELINE
Initial SICP (7/72):	762 psi	Gas Cum: Current (10/96)	5.7 Bcf 172 Mcf/d	GWI:	59.90%	EPNG
Current SICP (8/93):	292 psi	Oil Cum:	53.2 Mbo	NRI:	50.23%	
		Current (10/96)	0 Bo/d	SJBT:	9.38%	