Submit 3 Copies

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources Department to Appropriate Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St. 30-045-11010 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE X STATE L DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.) Culpepper Martin 1. Type of Well: TÍÒ. GAS WELL X well [2. Name of Operator 8. Well No. Taurus Exploration U.S.A., Inc. 3. Address of Operator 9. Pool name or Wildcat 2198 Bloomfield Highway, Farmington, NM 87401 Blanco MV/Basin DK 4. Well Location 790 South 1850 West Unit Letter Feet From The Line and Feet From The Line 6 31N 12W San Juan Range **NMPM** Township County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Lewis Pay ADD/Commingle OTHER: -12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. In accordance to DHC-2142, it is intended to ADD the Lewis pay and downhole commingle as follows: 1. MIRU. TOH and laydown MV tubing string. Release seal assembly and TOH. 2. TIH with packer milling assembly. Mill out baker model D at 4850'. TOH. 3. Set RBP at 4400'. Run GR-CBL-NEUTRON Log. Test casing to 3000 psi. 4. Selectively perf Lewis from 2900' to 3500'. Top of Huerfanito Bentonite at 2880'. 5. Fracture treat with 60 O Foam. 6. TIH and clean out with air mist. Retrieve RBP and TOH. 7. TIH and clean out to 6884'. Land tubing at 6800'. Install single wellhead. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Production Assistant 12/15/98 DATE TYPE OR PRINT NAME Monica Taylor TELEPHONE NO. 505-325-6800

DEPUTY OIL & GAS INSPECTOR, DIST. #3

APPROVED BY

TRIGINAL SIGNED BY CHEER HUSCH