or i0-5 No er 1983) For 'rly 9-331)		UNITED STAT MENT OF THE AU OF LAND MAN	INTERIOF	(Other Instructions on verse side)	5. LEASE	DESIGNATION AND 10-603-2033	
SUI (Do not use th	NDRY NO	TICES AND REI	PORTS ON pen or plug back -" for such propos	to a different reservoir.	Navaj		PRIBE NAME
OIL Y GAS					7. UNIT	AGREEMENT NAME	
WELL WELL NAME OF OPERATOR	OTHER				8. FARM	OR LEASE NAME	
Solar Petroleum, Inc.					Navaj	Navajo Tribe of Indians	
3. ADDRESS OF OPERATOR						9. WELL NO.	
		treet, Denver,			209		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' fSL & 1980' fWL						Many Rocks Gallup 11. SEC., T., E., M., OR BLE. AND	
					Secti	on 1-31N-17	الما
4. PERMIT NO.		15. ELEVATIONS (Sho	w whether DF, RT,	GR, etc.)		TY OR PARISE 13.	
	-		5285' GL		San J	luan	NM
•				()	`	······································	
.	Check A	oppropriate Box 10	Indicate Natu	re of Notice, Report, o			
	NOTICE OF INT	INTION TO:		SUBA	SEQUENT REPOR	TOF:	
TEST WATER SHUT	-OFF	PCLL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	<u> </u>	ALTERING CASING	
SHOOT OR ACIDIZE	<u> </u>	ABANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*	<u> </u>
REPAIR WELL		CHANGE PLANS		(Other) Casing I		lest e completion on W	X
. DESCRISE PROPOSED	OR COMPLETED OF	PERATIONS (Clearly state	all pertinent de	tails and also postinout de	tes, including	estimated date of s	tarting one
nent to this work.	sured up	on casing. He	osurface locations	or 15+ minutes.	rtical depths fo	or all markers and	zones perti-
nent to this work.	sured up	ionally drilled, give sub	osurface locations	and measured and true ve	D)	or all markers and	zones perti-
/30/88 - Pres	sured up (witness:	on casing. He	osurface locations	and measured and true ve	D)	or all markers and	zones perti-
/30/88 - Pres BLM	sured up (witness:	on casing. He	osurface locations	and measured and true ve	D)	or all markers and	zones perti-
/30/88 - Pres BLM 1000 - Fd 1000 - Fd 1000 - Fd 1000 - Fd	sured up (witness:	on casing. He	osurface locations	and measured and true ve	D) E	EP1 4 1388	zones perti-
/30/88 - Pres BLM	sured up (witness:	on casing. He	osurface locations	and measured and true ve	D) E	or all markers and	zones perti-
30/88 - Pres BLM SIGNED Steph (This space for Fee	witness: I	is true and correct Intington face use)	Id 1000# f	and measured and true ve	OIL	EP1 4 388 CON. DIV	Zones perti-
A 1 hereby certify the Signer Steph	witness: I	is true and correct Intington incouse)	Id 1000# f	for 15+ minutes.	OIL	EP1 4 388 CON. DIV	Zones perti-