UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Vells	/		
	5.	Lease Number		
		SF-078509		
. Type of Well	6.	If Indian, All. or		
GAS		Tribe Name		
	7.	Unit Agreement Name		
. Name of Operator				
MERIDIAN OIL		San Juan 32-9 Unit 8. Well Name & Number San Juan 32-9 U #40		
	8.			
Address & Phone No. of Operator				
PO Box 4289, Farmington, NM 87499 (505) 326-97	9.	API Well No.		
. Location of Well, Footage, Sec., T, R, M	1.0	30-045-11220 Field and Pool		
890'FSL, 890'FWL, Sec.30, T-32-N, R-9-W, NMPM	1	Blanco Mesaverde		
	11	. County and State		
		San Juan Co, NM		
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT	ICE, REPORT, OTH	ER DATA		
Type of Submission Type of	Action			
X Notice of Intent Abandonment	Change of I			
Subsequent Report Plugging Back	New Constru	oction Fracturing		
Casing Repair				
Final Abandonment Altering Casin				
tillar Abandonment Artering Cabin	g Conversion	to Injection		
That Abandonment Aftering dath		to Injection		
X Other - Tubing		to Injection		
X Other - Tubing		to Injection		
X Other - Tubing	repair	<u>.</u>		
X Other - Tubing 3. Describe Proposed or Completed Operations	repair	<u>.</u>		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su	repair bject well accord	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su	repair	ding to the attached		
Z Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su	repair bject well accord	ding to the attached		
Z Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su	repair bject well accord	ding to the attached		
X_ Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X_ Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X_ Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord	ding to the attached		
Z Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	repair bject well accord JAN 1 8 1988 OIL GON, D DIST, 3	ding to the attached		
3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram.	JAN 1 3 1988	ding to the attached		
X Other - Tubing 3. Describe Proposed or Completed Operations It is intended to repair the tubing in the su procedure and wellbore diagram. 4. I hereby certify that the foregoing is true and the foregoing is true and the foregoing is true and the foregoing is true.	JAN 1 3 1988	ding to the attached		
3. Describe Proposed or Completed Operations It is intended to repair the tubing in the surprocedure and wellbore diagram. 4. I hereby certify that the foregoing is true as signed of the surprocedure and the foregoing is true as signed of the surprocedure and the foregoing is true as signed of the surprocedure and signed of the surprocedure and signed of the surprocedure and supprocedure and wellbore diagram.	JAN 1 3 1938 OCCUPATION THE PROPERTY OF THE PROPERTY Administra	ding to the attached		
A I hereby certify that the foregoing is true as igned May Malhuel (VGW5) Title Regul	JAN 1 3 1988	ding to the attached		

WORKOVER PROCEDURE -- TUBING REPAIR

San Juan 32-9 Unit #40 DPNO 69891 Blanco Mesaverde Sec. 30, T32N, R09W San Juan County, New Mexico

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and MOI safety regulations.
- 2. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 3. POH with 2-3/8" tubing (188 jts). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations). Remove bull plug and perforated sub. PU and RIH with 4-3/4" bit and 5-1/2", 15.5# casing scraper to PBTD (5855'). TOH with bit and scraper. If any fill, TIH with hydrostatic bailer and CO or CO w/air. POH.
- 4. PU 5-1/2" RBP and RIH. Set @ 5300'. Load hole with 1% KCl water. Pressure test casing to 750#. (If casing does not test, dump 1 sx of sand on top of RBP. Notify Operations Engineer. Isolate failure and repair.) Release RBP and POH.
- 5. RIH open ended with 2-3/8", 4.7# tubing, SN one joint off bottom, (rabbit tubing in derrick before running in hole). Land tubing @ 5842'.
- 6. ND BOP, NU wellhead, rig down, move off location and restore location.

		Recommended:			
		Approval:	Operations Engineer		
			Drilling Superintendent		
CONTACTS:	Operations Engineer	Gaye V	√hite	326-9875	

San Juan 32-9 Unit #40

Current -- 11-28-95

DPNO: 69891 Blanco Mesaverde


890' FSL, 890 FWL

Sec. 30, T32N, R09W, San Juan County, NM Longitude / Latitude: 107.823105 - 36.950790

Spud: Completed: Elevation:

10-20-56 11-10-56

Logs:



10-3/4", 32.75# csg. set @ 177' Circ. 125 sx cmt to surface

2-3/8" EUE tbg. set @ 5842' Bullplugged w/3' perf sub (188 jts., 5830')

TOC @ 3200' (TS)

TOC @ 3400' (TS)

7-5/8", 26.4#, J55 csg. set @ 3733' cmt. w/250 sx. TOC @ 3200' (TS)

Cliffhouse @ 5399'

Menefee @ 5459'

Point Lookout @ 5770'

Mancos @ 5882

Cliffhouse Perfs @ 5423'-5427', 5431'-5444', 5451'-5457', 5478'-5486'

Frac'd w/55,100 gal water, 60,000# 40/60 sd.

Squeezed perf @ 5500' w/120 sx cmt.

Point Lookout Perfs @ 5774'-5780', 5792'-5796', 5806'-5818', 5828'-5842'.

Frac'd w/42,700 gat water, 55,000# 20/40 sd.

5-1/2", 15.5#, J55 csg. set @ 5911" Cmt. w/300 sx, TOC @ 3400' (TS)

Initial Potential:

Initial AOF: 8017 Mcf/d 11-9-56 981 Psig Initial SITP: 11-9-56 Last SITP: 410 Psig 8-16-93 Production History: Gas

Well Cum - 1995: As of 9/95

6-3/4" Hole

<u>Oil</u> 2.1 Bcf 13.1 Mbo 80 Mcf/d 0 bo

PBTD @ 5855' TD @ 5920'

> Ownership: GWI: 42.914664% NRI: 33.449535%

Pipeline: El Paso Natural Gas