UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

Sundry Notices and Repo	rts on Wells Staug-1 PN 1:50
	5. Lease Number
	GD 070507
6 77 11	070 FARMINGTON, NNE . If Indian, All. or
1. Type of Well	Tribe Name
GAS	N
	7. Unit Agreement Name
2. Name of Operator	
	San Juan 32-9 Unit
MERIDIAN OIL	
	8. Well Name & Number San Juan 32-9 U #28
3. Address & Phone No. of Operator	
PO Box 4289, Farmington, NM 87499 (505)	326-9700 9. API Well No. 30-045-11231
	10. Field and Pool
4. Location of Well, Footage, Sec., T, R, M	- '
1650'FSL, 1650'FWL, Sec.26, T-32-N, R-10-	11. County and State
	San Juan Co, NM
	San Stan Co, Ita
Type of Submission X Notice of Intent Abandon Recompl Subsequent Report Pluggin Casing Final Abandonment Alterin X Other - It is intended to repair the tubing in procedure and wellbore diagram	etion New Construction g Back Non-Routine Fracturing Repair Water Shut off g Casing Conversion to Injection Tubing repair

AUG 02 1995 Chip Harrador for DISTRICT MANAGER

WORKOVER PROCEDURE - TUBING REPAIR

San Juan 32-9 #28
DPNO 69872
Blanco Mesaverde
SW, Section 26, T32N, R10W
San Juan County, New Mexico
Latitude/Longitude: 36.953293 - 107.854660

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and MOI safety regulations.
- 2. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCl water as necessary. ND wellhead and NU BOP. Test BOP.
- 3. POH 2 3/8" tbg (201 jts). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations.) PU and RIH with 4-3/4" bit and 5-1/2" 15.5# casing scraper to PBTD (6325"). CO and POH.
- 4. PU 5-1/2" fullbore packer and RIH. Set @ 5630'. Pressure test casing to 1000#. (If casing does not test, notify Operations Engineer. Isolate failure and repair.) Release packer and POH.
- 5. RIH with open-ended 2 3/8" 4.7# tbg. Land @ 6302'.
- 6. ND BOP, NU wellhead, rig down, move off location, and restore location.

Recommende	d: <u>Vatricia Jomo</u> Summer Engineering Interr
Approval:	Production Superintendent

Contacts: Operations Engineer

Larry Dillon

326-9714

Summer Engineering Intern

Elizabeth Thomas

326-9582

PET

PERTINENT DATA SHEET 7/18/95

Cumulative as of 1995 Current Monthly Rate		32.1 Mbo 4 bo			5- 95	115 Mcf/d	0 bo		
RODUCTION HISTORY:	Gas	<u>Oil</u>			DATE OF LAST PRODUCTION	l: <u>Gas</u>	Oil		
VORKOVER HISTORY:	None								
STIMULATION:	Pt. Lookout Cliffhouse Menefee	1390 bbls, water 1404 bbls, water 1400 bbls, water	r and 60,000#	sand.					
PERFORATIONS	Pt. Lookout 6017'-6055', 6150'6182', 6275'-6322', 6275'-6322' - 4 SPF Cliffhouse 5689-5730' - 4 SPF Menefee 5832'-5855' and 5890'-5912' - 4 SPF								
LOGGING:	ES, GRL, INC	D., ML, TS							
FORMATION TOPS:	Kirtland Fruitland Pictured Cliffs Lewis Cliffhouse Menefee	,	3010' 3317' 3786' 3885' 5654 5722		Point Lookout Mancos	6026' 6215'			
Tubing	2 3/8"	4.7#	J55	6203'	201 jts. tbg.				
6 1/ 4"	5 1/2"	15.50#	J55	6360'		300 sx		4540' (T	
8 3/4"	7"	20#	J55	3820'		250 sx.		2390' (T	
<u>HOLE SIZE</u> 12 1/2"	<u>SIZE</u> 9 5/8"	<u>vveight</u> 25.4#	SW	282'	LQOIF.	250 sx.		Circ. to su	
CASING RECORD:	SJBT:		GRADE	DEPTH	EQUIP.	TOTAL DEPTH: PBTD: CEMENT	6360' 6325'	TOC	
OWNERSHIP:	GWI:				DRI∟LING:	SPUD DATE: COMPLETED:	11/6/55 1/21/56		
LOCATION:	1650' FSL, 1650' FWL Sec. 26, T32N, R10W San Juan County, New Mexico Latitude/Longitude: 36,953293 - 107,854660			INITIAL POTENTIAL: INITIAL SITP: LAST AVAILABLE:	15,776 988 405	AOF psig psig	Mcf/d 1/21/56 1/20/92		
					KI	3 : 6971'	405	14-211	
WELL TYPE:	Blanco Mesav	erde			ELEVATION: GI	L: 6961'			
				1	PROP. NUMBEF::	0023423			

San Juan 32-9 Unit 28

Current -- 7/17/95

DPNO: 69872 Blanco Mesaverde

1650' FSL, 1650' FWL

Sec. 26, T32N, R10W, San Juan Co., NM Latitude/Longitude: 36.953293 - 107.854660

Spud: 11-06-55

Completed: 01-21-56

