# UNITED STATES

CHILLD DILLED								
DEPARTMENT	OF	THE	INTERIOR					
BUREAU OF	LAN	ID M	NAGEMENT					

Sundry Noti	ices and Reports on Wel	1s7 2: 15		
l. <b>Type of Well</b> GAS		LACH NM	5. 6.	Lease Number SF-078513 If Indian, All. or Tribe Name
2. Name of Operator			7.	Unit Agreement Name
MERIDIAN ©IL			8.	
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM			9.	·
4. Location of Well, Footage, Se 929'FNL, 986'FEL, Sec.20, T-3				30-045-11318  Field and Pool  Blanco Mesaverde  County and State
12. CHECK APPROPRIATE BOX TO INT Type of Submission _X_ Notice of Intent	DICATE NATURE OF NOTICE Type of Ac  _X_ Abandonment Recompletion	tion Change o New Cons	f Pla	ans tion
Subsequent Report	Mon-Rout	ine 1	Fracturing	
Final Abandonment	Casing Repair Altering Casing Other -	Conversi	on to	o Injection
It is intended to plug and procedure and well			iol	The attached
		©[[L	FEB CO DIE	- 6 1935 D M. DIV. N. 3
I hereby certify that the Signed Manhula	foregoing is true and (LWD5)Title Regulato		Dat	te 1/13/95
(This space for Federal or State APPROVED BY CONDITION OF APPROVAL, if any:	e Office use) Title	Dat	A	APPROVED S AMENDED
				EB 02 1995

**NMOCD** 

#### San Juan 32-9 Unit NP #8

Mesaverde NE, Section 20, T-32-N, R-9-W San Juan Co., New Mexico

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and MOI safety rules and regulations.
- 2. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. POH and tally 2 3/8" tubing. If tubing is stuck, cut-off near 7" casing shoe. Visually inspect tubing, if it has heavy scale or is in poor condition then LD production tubing and PU 2 3/8" work string. Run gauge ring (7", 23#) to 5550'.
- 4. Plug #1 (Cliff House top, 5593' -- 5493'): Wireline set 7" cement retainer @ 5543'. TIH with open-ended tubing to 5543' Load well with water and circulate clean. Pressure test casing to 500#. Spot 20 sxs Class B cement above retainer to 5493'. POH.
- 5. Plug #2 (Pictured Cliffs top, 3692' -- 3592'): Spot 29 sxs Class B cement from 3692' -- 3592'.
- 6. Plug #3 (Fruitland top, 3227' 3127'): Spot 29 sxs Class B cement from 3227' -- 3127'.
- 7. Plug #4 (Kirtland top, 2706' -- 2606'): Spot 29 sxs Class B cement from 2706' -- 2606'. POH to 2500' and reverse circulate well clean.
- Plug #5 (Ojo Alamo top, 2482' -- 2382'): Perforate 4 holes @ 2482'. PU 7" cement retainer and RIH; set @ 2432'. Establish rate with water into perfs. Mix and pump 55 sxs Class B cement, squeeze 26 sxs cement outside casing and leave 29 sxs inside. POH with setting tool. Pressure test casing to 500#.
- 9. Plug #6 (Nacimiento top, 805' -- 705'): Perforate 4 holes @ 805'. PU 7" cement retainer and RIH; set @ 755'. Establish rate with water into perfs. Mix and pump 55 sxs Class B cement, squeeze 26 sxs cement outside casing and leave 29 sxs inside. POH with setting tool. Pressure test casing to 500#.
- 10. Plug #7 (Surface): Perforate 2 holes @ 210'. Establish circulation out bradenhead valve. Mix and pump approximately 71 sxs Class B cement down the 7" casing, circulate good cement out bradenhead valve. Shut in well and WOC.
- 11. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommend	led:
	Operations Engineer
Approval:	
	Production Superintendent

Restore location per BLM stipulations.

LWD/CRF/crf

12.

## San Juan 32-9 Unit NP #8

### P & A

Mesa Verde DPNO 69973

929' FNL, 986' FEL, Section 20, T-32-N, R-9-W, San Juan County, NM

Spud: 11-10-53

Completed: 12-30-53

Nacimiento @ 755'

Ojo Alamo @ 2432'


Kirtland @ 2656'

Fruitland @ 3177'

Pictured Cliffs @ 3642'

Cliff House @ 5543' Menefee @ 5652'

Point Lookout @ 5932'



## PERTINENT DATA SHEET

1/5/95

WELLNAME:	San Juan 32-9 Ui	nit NP #8			DP NUMBER:		69973			
WELL TYPE:	Mesaverde				ELEVATION:	GL: KB:	6809' 6820'			
LOCATION:	Sec. 20, T32N, R				INITIAL POTENTIAL:		1,260	Mcf/d		
San	San Juan County	, New Mexico			SICP:		813	psig		
OWNERSHIP:	GWI: NRI:	50.0000% 42.2500%			DRILLING:	C	SPUD DATE: COMPLETED: TAL DEPTH: PBTD:			11-10-53 12-30-53 6255' Open Hol
CASING RECORD:										
HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.		CEMENT	-		тос
12 1/2"	9 5/8"			160'	-		160 sx			Surfac
8 3/4"	7"			5566'			500 sx		Calc.	2622
Tubing	2 3/8"			6120						
FORMATION TOPS:	Nacimiento Ojo Alamo Kirtland Fruitland Pictured Cliffs Lewis Cliff House Menefee		755' 2432' 2656' 3177' 3642' 3706' 5543' 5652'		Point Looko Gallup Graneros Dakota	ut	5932'			
LOGGING:										
PERFORATIONS	None									
STIMULATION:	Shot 1,935 qts.	SNG 5625'	6255'							
WORKOVER HISTORY:	None									
PRODUCTION HISTORY:	<u>Gas</u>	<u>Oil</u>			DATE OF LAST PRODUC		Gas		<u>Oil</u>	
Cumulative as of 1994: Current:	171.4 MMcf 0 Mcf	0 Bbl 0 Bbl				July, 1	989 25 Mcf	0	Bbl	
PIPELINE:	EPNG	<u> </u>								

## San Juan 32-9 Unit NP #8

**CURRENT -- 12-29-94** 

Mesa Verde DPNO 69973

929' FNL, 986' FEL, Section 20, T-32-N, R-9-W, San Juan County, NM

Spud: 11-10-53

Completed: 12-30-53

Nacimiento @ 755'

Ojo Alamo @ 2432'

Kirtland @ 2656'

Fruitland @ 3177'

Pictured Cliffs @ 3642'

Cliff House @ 5543' Menefee @ 5652'

Point Lookout @ 5932'

