(SUBMIT IN TRIPLICATE)

Land Office Lease No. Alligon

Unit



UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY	Y NOTICES A	ND REPOR	TS ON V	VELLS	
NOTICE OF INTENTION TO DRILL				ac()	Still,
NOTICE OF INTENTION TO CHANGE	E PLANS	SUBSEQUENT REPO	RT OF WATER SHUT	-OFF	
NOTICE OF INTENTION TO TEST W	ATER SHUT-OFF	SUBSEQUENT REPO	RT OF SHOOTING O	R ACIDIZING	
MUTICE OF INTENTION TO RE-DRI	LL OR REPAIR WELL	SOBSEQUENT REPO	RT OF ALTERING CA	SING	
MOTICE OF INTENTION TO SHOOT	OR ACIDIZE	TODOCAGENI KEPOI	RI OF RE-DRILLING	OR REPAIR	
NOTICE OF INTENTION TO PULL OF	R ALTER CASING.	SUPPLEMENTARY W	TI OF ABANDONMEN	IT	A
NOTICE OF INTENTION TO ABANDO	ON WELL.		ELL HISTORY		
(INDIC	CATE ABOVE BY CHECK MARK	NATURE OF REPORT MORNING			
		OF REPORT, NOTIC	CE, OR OTHER DATA		
			Decembe	r 20	19 56
ell No. 11 is loca	ated 890 to two	[N], , son	· (T	.)	/
Section 23	<u> </u>	line and 990	ft. from	line of sec.	23
(1/2 Sec. and Sec. No.)	328	TV NMC	K	• •	
Vildeat			Meridian)		
(Field)	(County or	Sun Juan Subdivision)	lie	W Mexico	
ne elevation of the derrick	a ,	·		r Territory)	
and delifer					
ite names of and	DETAIL	S OF WORK			
	a objective en a la l				
ann expected depths to	ing points, and all other	weights, and lengths of p	roposed casings; in	dicate mudding iche	
	ing points, and all other	weights, and lengths of p er important proposed wo	roposed casings; in rk)	dicate mudding jobs,	cement-
ate names of and expected depths to				dicate mudding jobs,	cement-
2-5-56.				dicate mudding jobs,	cemenț-
2-5-56. his well was plugged	i and abandoned i	n the followin	g menner:		
2-5-56. his well was plugged l. Set 40 sa	i and abandoned i	n the followin	g menner:		
2-5-56. his well was plugged l. Set 40 sa collapsed	i and shandoned i	n the followin from 2611' - 2	g menner:		
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p	i and abandoned inches coment plug below 2711').	n the followin	g manner: 711' (Inter		
2-5-56. his well was plugged 1. Set 40 ss collapsed 2. Cut and p 3. Set 55 ss	i and abandoned in the common plug is below 2711'). ulled 9 5/8" case cks common plug	n the followin from 2611' - 2 ing from 802'.	g manner: 711' (Inter		
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa	i and abandoned in the case of	n the followin from 2611' - 2 ing from 802'. from 740' - 84	g manner: 711' (Inter	mediate casi	
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa	i and abandoned in the common plug is below 2711'). ulled 9 5/8" case cks common plug	n the followin from 2611' - 2 ing from 802'. from 740' - 84	g manner: 711' (Inter	mediate casi	
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa	i and abandoned in the case of	n the followin from 2611' - 2 ing from 802'. from 740' - 84	g manner: 711' (Inter	mediate casi	
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged	i and abandoned inches coment plug in below 2711'). Willed 9 5/8" case case plug inches coment plug inches coment plug in atte over surface	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-56. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged	i and abandoned inches coment plug in below 2711'). Willed 9 5/8" case case plug inches coment plug inches coment plug in atte over surface	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-56. his well was plugged 1. Set 40 as collapsed 2. Cut and p 3. Set 55 as 4. Set 40 as 5. Welded plugged	i and abandoned in the case of	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-50. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged	i and abandoned in the case of	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-50. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged understand that this plan of work r spany E. F. so Nature ress Box 997	i and abandoned in the case comment plug is below 2711'). willed 9 5/8" case case plug in the case comment plug is at a over surface in the case comment plug is at a comment plug in the case comment plug is at a comment plug in the case comment plug in the case comment plug is at a comment plug in the case case case comment plug in the case case case case case case case cas	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-50. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged	i and abandoned in the case comment plug is below 2711'). willed 9 5/8" case case plug in the case comment plug is at a over surface in the case comment plug is at a comment plug in the case comment plug is at a comment plug in the case comment plug in the case comment plug is at a comment plug in the case case case comment plug in the case case case case case case case cas	n the followin from 2611' - 2 ing from 802'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	
2-5-50. his well was plugged 1. Set 40 sa collapsed 2. Cut and p 3. Set 55 sa 4. Set 40 sa 5. Welded plugged inderstand that this plan of work r spany E. F. so Nature	i and abandoned in the case comment plug is below 2711'). willed 9 5/8" case case plug in the case comment plug is at a over surface in the case comment plug is at a comment plug in the case comment plug is at a comment plug in the case comment plug in the case comment plug is at a comment plug in the case case case comment plug in the case case case case case case case cas	r the following from 2611' - 2 ing from 862'. from 740' - 84 from surface to with 4" line 1	g manner: 711' (Inter 0'. 0 50'. cipe marker	mediate casi	

A Second Contraction