

(SUBMIT IN TRIPLICATE) ✓

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 073039  
Unit E 1/4 Sec. 22, T. 32 N.  
R. 11 W. N.M.P.M.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	<input type="checkbox"/>	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	<input type="checkbox"/>	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	<input type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	<input type="checkbox"/>	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<input type="checkbox"/>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 15, 1952

Well No. Horton # 2 is located 990 ft. from N line and 990 ft. from E line of sec. 22  
11 1/4 22 32 N 11 W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Blanco San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6464 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill with rotary tools to top of Cliff House sandset pipe - and drill with rotary using gas through Cliff House, Menefee and Point Lookout - if available - if not, cable tools, shoot- clean out for gas completion in Mesa verde formation.

Casing program:

200'-10 3/4 cemented to surface

4800'-7" or 5 1/2 cemented w/200 sfs

5500'-2" tubing

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Kenneth A. Archison

Address 1105 Reserve Loan Life Bldg.,

Dallas 1, Texas

By E. F. Casinger  
Title Superintendent