•	ATES	STA	ED :	TI	បា
NTERIOR	E I	TH	OF	ENT	EPARTM
AGEMENT	MAN	ND	LAI	OF	BUREAU

Sundry Notices and Rep	ports on Wells	7.1 0: 13°	
1. Type of Well GAS		5. 5. 6.	Lease Number NM-014227 JF-079/4 If Indian, All. or Tribe Name
	.	7.	Unit Agreement Name
2. Name of Operator MERIDIAN OIL			San Juan 32-9 Unit
		8.	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (50	9.	San Juan 32-9 U #56 API Well No. 30-045-11497	
4. Location of Well, Footage, Sec., T, R, 1	<u> </u>	10.	Field and Pool
1550'FSL, 1600'FWL, Sec.12, T-32-N, R-1	11.	Blanco Mesaverde County and State	
			San Juan Co, NM
13. Describe Proposed or Completed Opera It is intended to repair the tubing			
procedure and wellbore diagra		-	
		1	The second secon
			2 GENVED AUG 2 3 1985
		0.	IL GONE SUN.
14. I hereby certify that the foregoing			
Signed Japan Stathield (LWD5) Ti	tle <u>Regulatory Ac</u>	dministrato	<u>r</u> Date 8/14/95
(This space for Federal or State Office us APPROVED BY		_ Date 🛕	PPROVED
CONDITION OF AFFROVAL, IT ally.			ALIC 1 8 1995

AUG 1 8 1995
/s/ Ken Townsend
UISTRICT MANAGER

PERTINENT DATA SHEET 8/1/95

WELLNAME:	San Juan 32-9 Unit 56			DP NUMBER: PROP. NUMBER:	69955 0023423			
WELL TYPE:	Blanco Mesave	rde			ELEVATION: GL:			
LOCATION:		R10W nty, New Mexico			INITIAL POTENTIAL:	3,320	AOF	Mcf/d
	Latitude/Longiti	ude: 36.996096	4 - 107.83763	1	INITIAL SITP: LAST AVAILABLE SITP:	985 300	psig psig	10/31/57 8/15/93
OWNERSHIP:	GWI: NRI: SJBT:	42.9146% 33.4495% 0.4158%			DRILLING:	SPUD DATE: COMPLETED: TOTAL DEPTH: COTD:	6/17/67 10/7/57 6078' 6010'	
CASING RECORD: HOLE SIZE	SIZE	WEIGHT	GRADE	DEPTH	EQUIP.	CEMENT	0010	TOC
12 1/4"	10 3/4"	32.75#	sw	171'		150 sx.		Circ. to surf
9 7/8"	7 5/8"	26.4	J55	3832'		250 sx.		2420' (TS)
6 3/4"	5 1/2*	15.5#	J55	6071'		300 sx.		3400'(TS)
	2 3/8"			5994'	200 jts.			1.00(10)
FORMATION TOPS:	Ojo Alamo Kirtland Fruitland Pictured Cliffs Lewis Cliff House Menefee		2645' 2747' 3165' 3528' 3625' 5457 5521		Point Lookout Mancos	5839' 6045'		
LOGGING:	ES, GRL, Ind.,	ML TS						
PERFORATIONS	5770'-5780', 58	08'-5838', 5896	i'-5924', 5946'	-5970', 5976'-5	5992' - 20 JPF			
STIMULATION:	80,000 gal. wat	er, 80,000# 20/-	40 sand, flush	with 10,000 g	al. water			
WORKOVER HISTORY:	Lost 2500' of wi	ireline during co	mpletion. No	record of reco	very.			
PRODUCTION HISTORY:	Gas	<u>Oil</u>		DA	TE OF LAST PRODUCTION:	Gas	Oil	
Cumulative as of 1995: Current:	345.6 MMcf 192 Mcf/m	50 bo 0 bo			5- 95	6 Mcf/d	0 bo	

WORKOVER PROCEDURE - TUBING REPAIR

San Juan 32-9 #56
DPNO 69955
Blanco Mesaverde
SW, Section 12, T32N, R10W
San Juan County, New Mexico
Latitude/Longitude: 36.9960964 - 107.837631

- Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and MOI safety regulations.
- 2. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCI water as necessary. ND wellhead and NU BOP. Test BOP.
- 3. POH 2 3/8" tbg (200 jts). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations.) PU and RIH with 4-3/4" bit and 5-1/2" 15.5# casing scraper to COTD (6010'). CO and POH.
- 4. PU 5-1/2" fullbore packer and RIH. Set @ 5650'. Pressure test casing to 1000#. (If casing does not test, notify Operations Engineer. Isolate failure and repair.) Release packer and POH.
- 5. RIH with open-ended 2 3/8" 4.7# tbg. Land @ 5980'.

6. ND BOP, NU wellhead, rig down, move off location, and restore location,

Summer Engineering Intern
Approval:

Approvai.

Recommended a

Production Superintendent

Contacts: Ope

Operations Engineer

Larry Dillon

326-9714

Summer Engineering Intern

Elizabeth Thomas

326-9582

PET

San Juan 32-9 Unit #56


Current -- 7-18-95

DPNO 69955 Blanco Mesaverde

1550' FSL, 1600' FWL Sec. 12, T32N, R10W, San Juan Co., NM Latitude/Longitude: 36.9960964 - 107.837631

Spud: 06-17-57

Completed: 10-07-57



TD @ 6078'