

BURLINGTON RESOURCES

SAN JUAN DIVISION

RECEIVED
AUG 3 1998
OIL CON. DIV.
DIST. 3

July 31, 1998

New Mexico Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505

Att: Mr. Roy Johnson

Dear Mr. Johnson:

This is an application for variance to Rule 107 Section J. We intend to workover and drill additional hole in the following wells in the Pictured Cliffs formation, run 3 1/2" casing and cement, and run no tubing.

Pipkin #4	NE Section 18, T-27-N, R-10-W	30-045-06556
Huerfanito Unit #49	NE Section 35, T-27-N, R-9-W	30-045-06155
Huerfanito Unit #25	SE Section 4, T-26-N, R-9-W	30-045-05998
Huerfanito Unit #24	SW Section 4, T-26-N, R-9-W	30-045-06030
Huerfano Unit #47	NE Section 9, T-26-N, R-9-W	30-045-05971
McConnell #2	SE Section 13, T-26-N, R-9-W	30-045-05816
McConnell #3	NE Section 13, T-26-N, R-9-W	30-045-05854

In addition, we intend to workover the following Pictured Cliffs wells which currently have 3 1/2" casing. We will stimulate and fracture treat these wells, and will run no tubing back in the wells.

Summit B #5	NW Section 33, T-29-N, R-11-W	30-045-60273
Whitley #1	NW Section 17, T-27-N, R-9-W	30-045-06531
Aztec #6	SE Section 14, T-28-N, R-11-W	30-045-07393
Mangum #3	SE Section 28, T-29-N, R-11-W	30-045-07810
Atlantic C #8	A NE Section 31, T-31-N, R-10-W	30-045-20137
Florance #8	NW Section 20, T-30-N, R-9-W	30-045-20462
Pierce #9	NW Section 7, T-30-N, R-9-W	30-045-20475
Sunray B #7	SW Section 15, T-30-N, R-10-W	30-045-20846
Sunray A #5	SE Section 10, T-30-N, R-10-W	30-045-20894
Summit #7	SE Section 34, T-29-N, R-11-W	30-045-21530

These tubingless completions are desirable as they allow Burlington to economically produce reserves from the tight, low pressure Pictured Cliffs formation. Significant cost savings are realized using this method. The 3 1/2" casing string will allow the wells to produce at a higher rate than can be realized through smaller tubulars, and also carry less risk during any subsequent workover operations.

Mr. Roy Johnson
New Mexico Oil Conservation Division
Page Two
July 31, 1998

RECEIVED
AUG 3 1998
OIL CON. DIV.
DIST. 3

All the listed wells meet the following criteria:

- are in proven fields
- are less than 5000' total depth
- do not have corrosive or pressure problems
- are not dual completions
- will not produce any liquids or condensate (dry gas only)

Attached is a pertinent data sheet and wellbore schematic for each well. Please let me know if you require any additional information for these wells.

Sincerely,

BURLINGTON RESOURCES



Peggy Bradfield
Regulatory/Compliance Administrator

xc: NMOCD - Aztec District Office

Summit B # 5
Pertinent Data Sheet

RECEIVED
AUG 3 1998

API #: 300456027300

OIL CON. DIV.

Location: 1650 ' FNL & 1650 ' FWL, Unit F, Section 33, T29N, R11W, San Juan County, New Mexico **DIST. 3**

Latitude: 36 ° - 41.1 ' **Longitude:** 107 ° - 59.98 '

Field: Fulcher Kutz PC

Elevation: 5,527 ' GL
5,534 ' KB

TD: 1,783 '
PBTD: 1,750 '
DP #: 32203A
Lease: NM 9843220
GWl: 100 %
NRI: 87.5 %
Prop#: 71264100

Spud Date: 3/8/46

Compl Date: 4/1/47

Initial Potential: 1620 Mcfd

Original SIP: ? psi

Casing Record:

<u>Hole Size (In.)</u>	<u>Csg Size (In.)</u>	<u>Wt. (#'s) & Grade</u>	<u>Depth Set (Ft.)</u>	<u>Cement (Sx.)</u>	<u>Cement (Top)</u>
16.5 est	15 1/2	60 J-55	56	10	Surf @ 75% eff.
7 7/8	5 1/2	14 J-55	1,630	40	1395' @ 75% eff.
4 3/4	3 1/2	10.3 C-75	1,781	175	circ to surf.

Tubing Record:

<u>Tbg. Size</u>	<u>Wt. & Grade</u>	<u>Depth Set</u>	<u># Joints</u>	<u>Comments</u>
1 1/4"	2.6 J-55	1,665 '	51	

Formation Tops:

Ojo Alamo: 432 ' All Tops are Estimated
Kirtland Shale: 494 '
Fruitland: 1,214 '
Pictured Cliffs: 1,628 '

Logging Record:

Original Stimulation: Original: SOH w/55 qts SNG, Restim: Perf'd 1636,40,44,48,52,56,60,64,68,82,86,80, SWF w/41,850 gal wtr, 55,500# 20/40 sd

Workover History: 11/11/83: 3-1/2 Restim (see above Stimulation)

Production History: 5/98 PC capacity: 12 MCF/D. 5/98 PC cum: 1,338 MMCF.

Pipeline: WFS

File: Q:\area\pcteam\1998\well\data\restim\RSTMPERT

Summit B # 5

Section 33 F, T-29 -N R-11 -W
San Juan, New Mexico

Fulcher Kutz Pictured Cliffs Field Wellbore Schematic

