# UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF	LAND MANAGEMENT		
Sundry Notic	es and Reports on Wells		
		5.	Lease Number
1. <b>Type of Well</b> GAS		6.	SF-077652  If Indian, All. or  Tribe Name
0/10		7.	Unit Agreement Name
2. Name of Operator		•	
SOUTHLAND ROYALTY COMPAN	Y	8.	Well Name & Number
3. Address & Phone No. of Operato	r	0.	East #13
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	<b>API Well No.</b> 30-045-20447
4. Location of Well, Footage, Sec	, T, R, M	10.	Field and Pool
1160'FSL, 1560'FWL, Sec.24, T-			Basin Fruitland Coal/ Aztec Pictured Cliffs
		11.	County and State
			San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDI	CATE NATURE OF NOTICE, REPO	RT, OTHER	DATA
Type of Submission	Type of Action		
_X_ Notice of Intent		inge of Pla Construct	
Subsequent Report	Plugging Back Nor	-Routine	Fracturing
	Casing Repair Wat	er Shut o	ff
Final Abandonment	Altering Casing Cor	iversion to	o injection
13. Describe Proposed or Comple	eted Operations		
	abandon the subject well ac	cording to	o the attached procedur
and wellbore diagra	am.		
		7	Wilder angles day is described by the service of th
		F	)Eachtain
		וח	)eceiven
		Ш	MAR 2 0 1995
		(0)	DIST. 2
		State of the state of	and the second of the second o
14. I hereby certify that the	foregoing is true and corre	st.	<del></del>
signed Serry Deadhula	(LWD4)Title Regulatory Af	<u>fairs</u> Da	te 3/1/95
(This space for Federal or State			
APPROVED BY	Title	Date _	
CONDITION OF APPROVAL, if any:		API	PROVED
		/ 1 1	The state of the s

MARI 1995.

DISTRICT MANAGER

#### East #13

Basin Fruitland Coal / Pictured Cliffs SW, Section 24, T-31-N, R-12-W San Juan Co., New Mexico

**Note:** All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM and MOI safety rules and regulations.
- 2. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and load with water. ND wellhead and NU BOP and stripping head; test BOP.
- 3. POH and tally 2 3/8" tubing. POH and visually inspect.
- 4. Plug #1 (Pictured Cliffs top -- Fruitland perfs and top, 2073' -- 2540'): RIH with open ended tubing to 2540' or as deep as possible. Pump 15 bbls water down tubing. Mix 55 sxs Class B cement (long plug, 50% excess) and spot a balanced plug from 2540' -- 2073'. POH with tubing and WOC. RIH and tag cement. Pull above cement and circulate well clean. Pressure test casing to 500# psi. POH with tubing.
- 5. Plug #2 (Kirtland/Ojo Alamo tops, 860' -- 1009'): Perforate 4 holes @ 1009'. TIH with 4 1/2" CR and set @ 959'. Establish rate with water into perforations with bradenhead valve open. Set Plug #2 with 51 sxs Class B cement. Squeeze 35 sxs outside casing and leave 16 sxs inside. POH and LD tubing. Pressure test tubing to 1000# psi.
- 6. Plug #4 (Surface): Perforate 2 holes @ 164'. Establish circulation out bradenhead valve. Mix and pump Class B cement down 4 1/2" casing, circulate good cement out bradenhead valve (calculated volume 48 sxs w/ no excess). Shut in well and WOC.
- 7. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.
- 8. Restore location per BLM stipulations.

Re	ecommended:	
		Operations Engineer
Aş	oproval:	
·	•	Production Superintendent

LWD/CRF/crf

### East #13


#### P&A

#### Basin Fruitland Coal -- DPNO 15404B Pictured Cliffs -- DPNO 15404A

#### 1160' FSL, 1560' FWL, Section 24, T-31-N, R-12-W, San Juan County, NM

Spud: 5-7-69

Completed: 6-4-69



Ojo Alamo @ 910

Kirtland @ 959

Fruitland @ 2123\*

Pictured Cliffs @ 2547

# **PERTINENT DATA SHEET**

3/1/95

WELLNAME:	East #13				DP NUMBER:		15404B 15404A	(FTC) (PC)	
WELL TYPE:	Basin Fruitland Pictured Cliffs	Coal			ELEVATION:	GL: KB:	6606' 6076'		
LOCATION:	1160' FSL, 1 Sec. 24, T31N, San Juan Coun		0		INITIAL POTENTIAL:	AOF	 184	Mcf/d Mcf/d	(FTC) (PC)
					INITIAL SICP:			(FTC) (PC)	
OWNERSHIP:	GWI: NRI: SJBT:	FTC 25.0000% 21.7500% 75.0000%	<u>PC</u>  		DRILLING:	C	SPUD DATE: OMPLETED: FAL DEPTH: PBTD:		05-07-69 06-04-69 2605' 2540'
CASING RECORD:								<del></del>	
HOLE SIZE	SIZE	WEIGHT	GRADE	<u>DEPTH</u>	EQUIP.		EMENT		тос
12 1/4"	8 5/8"	2 <b>4#</b>	J55	114'	-		60 sx	Circ.	Surfac
6 3/4"	4 1/2"	9. <b>5#</b>	J55	2605'			250 sx	Calc.	1003
Tubing (FTC)	2 3/8"	4.7#	J55	2508'					
	(FTC	C) 1 jt., seatin	g nipple (	@ 2478', 7	78 jts. tubing (total of 709 jts	2 3/8")		·	
FORMATION TOPS:	Ojo Alamo Kirtland Fruitland Pictured Cliffs Lewis Cliff House Point Lookout		910' 959' 2123' 2547'		Gallup Greenhorn Graneros Dakota				
LOGGING:	GR-CCL, NCL,	ES-Induction				_			
PERFORATIONS	FTC 2448' 25								
	ETC 5 000	I. 2% KCL. 25	,000 gal.	methanol	, 7,895 gal. 15% HCL, & 33	gai. FS2			
STIMULATION:	PC 35,000 ga	l. water & 25.0	000# 10/2	0 sand					
STIMULATION: WORKOVER HISTORY: Aug-90	PC 35,000 ga	I. water & 25.0	000# 10/2 	ell, ran con	relation log, set CIBP @ 254 C zone. Ran 2 3/8", 4.7#, Jt	-0' PT casii 55 tubing 8	ng 300#; OK alanded @ 2	. Ran GR-0 508'.	CCL & NCL
WORKOVER HISTORY: Aug-90 PRODUCTION HISTORY:	Fruitland Coal (Spot 150 gal. Ho	Recompletion	n: Kill we	ell, ran con fraced FT	relation log, set CIBP @ 254 C zone. Ran 2 3/8", 4.7#, Jt	55 tubing 8	ng 300#: OK landed @ 2 Gas	. Ran GR-C 508'.	CL & NCL
WORKOVER HISTORY: Aug-90	Fruitland Coal (	Recompletion CL @ 2530'.   Oil 0 Bbo	000# 10/2 	ell, ran con fraced FT	C zone. Ran 2 3/8", 4.7#, J	55 tubing 8	landed @ 2	508'. <u>Oil</u>	
WORKOVER HISTORY: Aug-90  PRODUCTION HISTORY: Cumulative as of 1994:	Fruitland Coal (Spot 150 gal. Ho	Recompletion CL @ 2530'.    Oil O Bbo O Bbo	n: Kill we Perfed &	ell, ran con fraced FT	C zone. Ran 2 3/8", 4.7#, J	ON:	Gas	<b>OII</b>	(FTC)

## East #13


#### **CURRENT -- 2-21-95**

Basin Fruitiand Coal — DPNO 15404B Pictured Cliffs — DPNO 15404A

1160' FSL, 1560' FWL, Section 24, T-31-N, R-12-W, San Juan County, NM

Spud: 5-7-69

Completed: 6-4-69



Ojo Alamo @ 910'

Kirtland @ 959

Fruitland @ 2123

Pictured Cliffs @ 2547